CHAPTER 5

QUALITY ASSURANCE/ANALYSIS

Chapter Objective: Upon completion of this chapter, you will have the knowledge to recognize the purpose of the Naval Aviation Maintenance Discrepancy Reporting Program (NAMDRP), identify the reports covered by the NAMDRP, recognize the responsibilities of the Data Analyst, and identify the important role that analysis plays in support of the Naval Aviation Maintenance Program (NAMP). You will also be able to identify the source documents used in the Maintenance Data System (MDS), and recognize the key reports generated by the MDS.

The quality assurance/analysis (QA/A) division is staffed with a relatively small group of highly skilled personnel. These permanently assigned personnel under the QA/A officer are responsible for conducting and managing the QA/A effort of the department. The maintenance personnel assigned to QA/A are known as quality assurance representatives (QARs). To obtain more efficient use of information collected by the Maintenance Data System (MDS), and to increase the scope of QA/A, a qualified data analyst is assigned. The primary duty of the data analyst is to perform all MDS functions of QA/A. The data analyst will not be assigned the duties of technical publications librarian or QAR. It is also the responsibility of QA/A personnel to maintain the central technical publications library, which was previously discussed in chapter 3 of this TRAMAN.

NAVAL AVIATION MAINTENANCE DISCREPANCY REPORTING PROGRAM (NAMDRP)

This program is the method by which hazardous deficiencies in material and publications, substandard workmanship, and improper quality assurance (QA) procedures are reported,

As an AZ3 or AZ2 you should know the purpose of each of the discrepancy reports; be able to review them for completeness, correct phraseology, part number identification, and

nomenclature; and furnish information from the aircraft logbook for their preparation. Chapter 6 of this TRAMAN provides information as to what is recorded in the various sections of the aircraft logbook. If you are the AZ who is responsible for the preparation of discrepancy reports, you should be familiar with the preparation and maintenance of the aircraft logbook as well as the preparation of NAMDRP reports.

The reports described in this section provide a method for reporting safety situations and quality deficiencies that require special attention and/or prompt corrective action. The QA/A division is responsible for managing the NAMDRP. QA/A will assist the work centers in determining if one or more reports are needed for any maintenance problem or situation occurring in the activity and review all reports to ensure they are accurate, clear, concise and comprehensive. The QA officer should review all of the reports listed below:

- Hazardous Material Report (HMR). This report provides a standard system for reporting material deficiencies. These deficiencies, if not corrected, could result in death or injury to personnel, or damage to or loss of aircraft, equipment, or facilities.
- Explosive Mishap Report (EMR). This report provides a standard system for reporting explosive incidents, malfunctions, and dangerous defects (referred to as explosive mishaps)

involving explosive systems (ordnance and cartridge-actuated devices), launch devices (devices used to launch or fire explosive systems), and armament weapons support equipment (AWSE). An explosive mishap is defined as any condition involving explosive systems, launch devices, or AWSE. These conditions, if not corrected, could result in death or injury to personnel, or damage to or loss of aircraft, equipment or facilities.

- Engineering Investigation (EI). EIs provide an investigation process that determines the cause of fleet-reported, equipment/material failures. It is a material analysis inspection or an engineering assistance investigation.
- Quality Deficiency Report (QDR). This report provides maintenance activities with a method for reporting deficiencies in new material or newly reworked material.
- Aircraft Discrepancy Report (ADR). This report provides a direct method for reporting discrepancies in quality assurance procedures to naval aviation depots (NAVAVNDEPOTs) and civilian contractors performing maintenance on aircraft.
- Technical Publication Deficiency Report (TPDR). This report provides a simplified procedure for reporting technical publication safety hazards and routine deficiencies.

Safety is the primary consideration for reports discussed in this section. If a report being submitted meets the criteria for an HMR/EMR and warrants an EI request or category (CAT) I QDR, it should be transmitted as a dual message report; for example, EMR/EI request. All HMRs, EMRs, EI request, and QDRs are submitted to the cognizant field activity (CFA). All supplemental data submitted in conjunction with this program will identify the original submitting activity's report serial number and message date-time group. Copies of reports are retained for 1 year.

A NAMDRP message report is prepared and submitted only under one or more of the following six conditions:

- 1. When an explosive/accident/incident/malfunction is involved.
- 2. When the existence of a known condition which, if not corrected, will or could result in

death or injury to pilot, crew, maintenance personnel, or other persons or loss of aircraft. This report is to be made by priority message within 24 hours of discovery.

- 3. When an urgent change is required to safety or loading or handling instructions to prevent a hazardous condition from occurring.
- 4. When urgent action or assistance is required or requested.
- 5. When a condition is detected that allows, due to the design of a part or component, incorrect installation. This condition can be or has been easily accomplished, and system malfunction or failure was the result (Murphy's Law).
- 6. When damage to an aircraft occurs due to failure of support equipment (SE).

CFA response to an EMR, HMR, and all combined reports, such as HMR/EI, must be provided to the requesting activity within 72 hours of their receipt of the request; within 5 working days after receipt of a routine EI request, CAT I QDR, or CAT I TPDR; within 10 working days after receipt of a CAT II QDR; as soon as possible, but not later than 45 days after receipt of an ADR (30 days in the case of aircraft reworked at a NAVAVNDEPOT); and within 30 days after receipt of a CAT II TPDR.

PREPARATION OF NAMDRP MESSAGE REPORTS

As an AZ you may be required to submit a NAMDRP report in the course of your duties. Most often, however, you will be required to type a smooth report prepared in a rough form by another person attached to the maintenance activity.

The following content and format applies to the HMR, EMR, EI request, and CAT I QDR message reports. You should note that the spaces on these reports are numbered consecutively from 1 to 22. The basic data for each space is shown below. Detailed procedures for preparation, security classification, and forwarding of completed NAMDRP message reports are contained in the latest edition of OPNAVINST 4790.2.

- 1. Reporting custodian/unit identification code (UIC).
- 2. Cognizant field activity (CFA) for failed item. Enter the aircraft CFA when reporting common/general material not installed on, or peculiar to, specific aircraft.

- 3. Report control number (RCN). Report control numbers begin with 0001 at the beginning of each calendar year and progress consecutively throughout the year. Permanent detachments (detachments with OINCs, for example, LAMPS, HC) will assign report control numbers independently of the parent activity.
- 4. Julian date deficiency discovered/location of reporting unit. Omit location if entry will cause message to become classified.
- 5. National stock number. The correct national stock number, including all prefixes and suffixes of the item being reported, is entered in this space. This may require the use of catalogs and various manuals.
- 6. Nomenclature. The noun name of the item being reported is entered here. If necessary, reference should be made to the IPB for correct terminology.
- 7, For new material, indicate manufacturer's name and code and the shipper's name; for reworked material, the last rework facility.
- 8. Manufacturer's part number. The manufacturer's part number of the failed item is entered in this space. This information is normally found on the nameplate attached to the part. If not on the nameplate, refer to the SRC card, or to the latest applicable IPB.
- 9. Serial/lot/batch number. The serial/lot/batch number of the item being reported is entered in this space. This is usually found on the nameplate of the part or on the shipping container of lots and batches.
- 10. Contract/purchase order/document number (on shipments from government service administration facilities, include contract, purchase order, and requisition number). The contract number can normally be found on the item nameplate, SRC card, or shipping container, if available. The contract number is essential information for material replacement or cost adjustment under the warranty clause in government contracts.
- 11. New/reworked/overhauled, if known. This item relates to item 6.
- 12. Date manufactured/reworked (if applicable). This information may be obtained from decals, stamps, logbooks, or SRC cards.
- 13. Operating time at failure. Based on entry item 12, indicate the time material had been in service since new or rework when the deficiency was discovered. See item 12 for possible sources of information.
- 14. Government furnished material. (Yes or no, if QDR; N/A if not). This is material or

- equipment that has been furnished by the government to a contractor or government activity for installation in, use with, or in support of the aeronautical system during production, conversion, or modification.
- 15. Quantity. Quantity is a count of each individual unit of issue (QDR only, N/A if not). (A) received, (B) inspected, (C) deficient, (D) items in stock at activity.
- 16. Deficient item works on or with. In order of importance, enter (A) end item (B) next higher assembly.
- 17. Dollar value of deficient items (if known, otherwise UNK) and man-hours to repair.
 - 18. N/A
- 19. Item under warranty. Enter yes, no, or UNK as applicable.
- 20. Work unit code. Enter the work unit code as listed in block A22 of the VIDS/MAF,
- 21. Action/disposition. If holding for investigation, indicate holding activity, location, and time to be held at the activity; for example, holding exhibit 30 days for investigation at Building 4, Naval Supply Depot, Norfolk. If the exhibit is a cartridge-actuated device or an aircrew escape propulsion system (CADS/AEPS) item, provide the name of the holding station/ship ordnance department and the locally assigned turn-in document number. If no response is required, specify CFA response not required.
- 22. Details. The details should be entered as follows:
- a. Narrative description of abnormal function, known or probable causes, pertinent TDs not incorporated, comments or recommendations, and EI (if requested). Photographs to follow (if applicable).
- b. How safety of personnel or activity mission is affected.
- c. Number of similar deficiencies in like items reported by the originating activity; for example, 5 in the past 4 months.
- d. How deficiency was detected or confirmed; for example, visually or functional operation. Where deficiency was discovered; for example, maintenance/in flight.
- e. Storage/handling information, if applicable.
- f. Indicate if supporting documents will be supplied. When photographs are taken, place a ruler alongside the object so it will appear in each photograph. Measurements should also appear on sketches.
- g. Description of incorrectly identified new material, if applicable.

- h. If you are preparing an EMR, the list of items required in this section are too numerous to mention here. Refer to the latest edition of OPNAVINST 4790.2.
- i. The name, title, and AUTOVON number of the knowledgeable person to contact (if deployed, so indicate).
- j. Aircraft model and bureau number (if not already included).
- k. Aircraft engine, auxiliary power unit (APU), or support equipment gas turbine engine, model and serial number, time since new, time since overhaul, last overhaul activity, and number of overhauls (if applicable and not already included).

HAZARDOUS MATERIAL REPORT (HMR)

This report provides a standard method for reporting material deficiencies, which, if not corrected, could result in death or injury to personnel, or damage to or loss of aircraft, equipment, or facilities. An HMR priority precedence message (fig. 5-1) is submitted within 24 hours of discovery of one or more of the following conditions:

1. When a malfunction or failure of a component part that, if not corrected, could result in death or injury to personnel, or damage to or loss of aircraft, equipment or facilities.

```
FROM: NAS GREEN COVE SPRINGS FL
      NAVWPNCEN CHINA LAKE CA
TO:
       AIG FOUR TWO THREE
INFO: COMASWWINGPAC SAN DIEGO CA
       USS GOLDWATER
UNCLAS //N04790//
SUBJ: HAZARDOUS MATERIAL REPORT
MSGID/GENADMIN/AIMD//
REF/A/DOC/OPNAV/01JAN89//
AMPN/OPNAVINST 4790.2E//
RMKS/1, NAS GREEN COVE SPRINGS/00123
2. NAVWPNCEN CHINA LAKE CA
3. N00123-88-0003
4. 8239/GREEN COVE SPRINGS
5. 2RH 1670-00-127-5598
6. NES-12H PARACHUTE ASSEMBLY
7. N/A
8. 107AS 106-1
   SERIAL NO. 211257
10. N/A
11. N/A
12. REPACKED 8016
13. 223 DAYS
14. N/A
15. N/A
16. S-3A
17. N/A
18 N/A
19. N/A
20 91A20
21. REPACKED IAW NA 13-1-6.2 AND RETURNED TO SERVICE.
22. A. SUBJ PARACHUTE LAST PACKED ON BOARD CV 58 INDUCTED FOR 224 DAY INSPECTION AT AIMD GREEN
       COVE SPRINGS, INSPECTION REVEALED FOLLOWING DISCREPANCY: LOWER PACK OPENING BANDS
       ROUTED OVER EPC LANYARD VICE UNDER.
   B. THIS CONDITION COULD HAVE SERIOUSLY IMPEDED PROPER OPERATION OF PARACHUTE DURING
       EJECTION.
   C. ZERO
   D. VISUALINSPECTION/MAINTENANCE
   E. N/A
   F PHOTO AVAILABLE ON REQUEST
   H. N/A

    REDMOND PRC, AUTOVON 951-7650

   J. THROUGH L. N/A//
```

Figure 5-1.-Sample Hazardous Material Report (HMR).

- 2. When urgent or when assistance is required and corrective action must be completed at an early date because of operational commitments.
- 3. When a condition is detected that could cause incorrect installation and subsequent system malfunction due to the design of a part.
- 4. A potential or experienced in-flight or onthe-ground loss of aircraft parts in which maintenance/material factors are involved. The terminology "Things Falling Off Aircraft (TFOA)" is used when referring to such incidents. TFOA includes incidents such as a FODed engine which sheds parts.

EXPLOSIVE MISHAP REPORT (EMR)

This report provides a standard method for reporting explosive incidents, malfunctions, and dangerous defects, which, if not corrected, could result in death or injury to personnel, or damage to or loss of aircraft, equipment or facilities, An EMR priority precedence message (fig. 5-2) is submitted within 24 hours of discovery under one or more of the following conditions:

1. When a malfunction or failure of an explosive system, launch device, or AWSE is detected, which, if not corrected, could result in death or injury to personnel, or damage to or loss

```
FROM: FITRON SEVEN ONE
       COMPAGNISTESTOEN PT MUGU CA
TO:
       AIG FOUR TWO THREE
       AIG SEVEN SIX TWO ZERO
       COMTACWINGSLANT OCEANA VA
COMCARAIRWING EIGHT
EMPO:
       USS FRANKLIN
UNCLAS //N04790//
SUBJ: EXPLOSIVE MISHAP REPORT
MRGID/GENADMIN/VF-71 QA//
REF/A/DOC/OPNAV/OLJAN89//
REP/B/DOC/OPNAV/03MAR89//
NARRAREF A IS OPNAVINST 4790.2E, REF B IS OPNAVINST 5102.1C#
RMKS/1, VF-71/34567
2. PACMISTESTCEN PT MUGU CA
   R34567-88-0040
   7365/DEPLOYED
   RE 1410-01-056-9405
   AIM-9L TACTICAL GUIDED MISSILE
   49956
   N/A
   SER, NO. KRE-0205
4
H. UNK
11. REWORKED
12. 20 APRIL 86
13. 137.9 HRS
14. N/A
16. F-14A
17. 58,000/UNK
18. N/A
19. UNK
20. 75M12
21. HOLDING 30 DAYS AT WEAPONS DEPT USS FRANKLIN (CV-58).
22. A. ARMING DEVICE WILL NOT STAY IN ARMED POSITION, GOES TO SAFE IN FLIGHT.
    B. POSSIBLE LOSS OF MISSION CAPABILITY.
    C. TWO IN LAST SIX MONTHS.
    D. VISUAL ON AIRCRAFT RECOVERY.
    E. THROUGH G. N/A
    H. (1) NONE
             VISIBILITY 5 MILES AND SCATTERED/WIND 9 KNOTS/TEMP 76 DEG F.
        (2)
             AIM-9L TACTICAL GUIDED MISSILE/SER.NO. KRE-0235/DODIC PA72/8E 1410-01-056-9405.
        (4) LAU-7/A-5 SER. NO.0032/AIRCRAFT STA. 1A.
        (5) N/A
        (6) 52
        17) SAFE/ARM SWITCH OF ARMING DEVICE WILL NOT STAY IN ARMED POSITION WHILE IN FLIGHT.
        (8) THROUGH (15), N/A
        (16) AIM-9L LOADED ON AIRCRAFT STA. IA AND 8A.
        AOC B.B. STACKER/ARMAMENT BRANCH CPO/DEPLOYED
        F-14A/161162
     K. AND L. N/A//
```

Figure 5-2.-Sample Explosive Mishap Report (EMR).

of aircraft, equipment or facilities. Any explosive mishap involving aircrew error must be reported using the latest edition of OPNAVINST 3750.6 or OPNAVINST 5102.1.

- 2. When a malfunction or failure of an explosive system is found to be caused by failed material. This report is a combined EMR/QDR or EMR/EI as appropriate.
- 3. When urgent action or assistance is required to correct a deficiency at an early date because of an operational commitment.
- 4. When an urgent change to ordnance loading or launch device/AWSE safety instructions is required to prevent a hazardous condition from occurring.
- 5. When a condition is detected that could cause incorrect installation and subsequent system malfunction due to the design of a part.

ENGINEERING INVESTIGATION (EI)

The EI comprises three types of investigation: disassembly and inspection, material analysis, and engineering assistance. Only the disassembly and inspection procedures will be discussed in this section since the procedures for requesting any of the three types of investigation are the same.

Engineering investigations (fig. 5-3) are requested by a routine precedence message within 5 working days after discovery of the deficiency, unless combined with an HMR/EI, under one or more of the following conditions:

- 1. When safety is involved. This includes EI requests prepared in conjunction with accidents/incidents, ground accidents/incidents, and impending malfunctions when it is evident that an unsafe condition exists.
- 2. When additional technical or engineering information is required to complete an accident report.
- 3. When aircraft readiness is seriously impaired due to poor material (including SE) reliability/maintainability/logistic support.
- 4. When a component is rejected by the Navy Oil Analysis Program (NOAP) after attempted authorized repairs are exhausted at the organizational and intermediate levels.

5. When specifically directed by higher authority.

All reguests for EIs are submitted to the CFA, which will study the history of similar equipment failures and determine the potential value of conducting an EI on the equipment in question. If the study indicates that an EI is not required, the CFA so informs (by message) the requesting activity. If the study indicates an EI is warranted, the CFA assigns a control number to the investigation and provides shipping instructions to the requesting and holding activities by message. Whether an EI is warranted or not, the CFA must respond by message within 5 calendar days after receipt of the EI request to the requesting activity. For an approved EI request, the CFA will follow up on equipment not received from the holding activity within 20 days. Activities should maintain each EI on file for a period of

QUALITY DEFICIENCY REPORT (QDR)

This report provides maintenance activities with a method for reporting deficiencies in new material or reworked material that may be attributable to nonconformance to contractual or specification requirements or substandard workmanship.

New material is defined as material procured under contract from industry or manufactured by an in-house facility that is still under warranty. All material, whether in actual operation or on the shelf, is considered new until the warranty expires.

Reworked material is that material overhauled, rebuilt, repaired, or modified by government or commercial activities but unproven in actual operations.

The category I (CAT I) QDR is a report on a quality deficiency, which will, or may, affect life or limb of personnel or impair the combat capabilities of the using organization or individual or that affects operational capability to the extent that mission accomplishment is jeopardized. The category II (CAT II) type of QDR is made on all other deficiencies that do not meet the criteria set forth in category I.

```
TO: NAVAVNDEPOT PENSACOLA FL
       AIG FOUR TWO THREE
INFO: COMSEABASEDASWWINGSLANT JACKSONVILLE FL
       COMHELSEACONWING ONE NORFOLK VA
      HELANTISUBRON LIGHT TWO THREE
       HELANTISUBRON LIGHT THREE ZERO
       HELANTISUBRON LIGHT THREE TWO
       HELANTISUBRON LIGHT THREE SIX
       HELANTISUBRON LIGHT THREE FOUR DET ONE
       USCOMSOLANT
UNCLAS //N04790//
SUBJ: ENGINEERING INVESTIGATION REQUEST
MSGID/GENADMIN/HSL-23 DET 2//
REF/A/DOC/OPNAV/01JAN89//
AMPN/OPNAVINST 4790.2E//
RMKS/1. HSL-23 DET 2/23456
2. NADEP PENSACOLA
3. V23456-88-0002
4. 8125/DEPLOYED
5. 2RH 1615-01-010-9102 BH
6. TAIL ROTOR GEARBOX
7. NADEPPENSACOLA
8. KG7165Z-5
9. SER 021-90M-91
10. N/A
11. REWORKED
12. REWORKED 18 NOV 87
13. 2359.6 SINCE NEW. 888.8 SINCE OVERHAUL
14. N/A
15. N/A
16. SH-2F
17. $7100.00/UNK
18. N/A
19. UNK
20. 26210
21. HOLDING ON USS ARTHUR W RADFORD FOR 30 DAYS FOR SHIPPING INSTRUCTIONS.
22. A. REMOVED ON ADVICE OF NOAP LAB NADEP NORFOLK DUE TO VERY HIGH IRON AND INCREASING
        COPPER CONTENT.
    B. POSSIBLE LOSS OF AIRCRAFT/AIRCREW.
    C. NONE
    D. OIL ANALYSIS
    E. THROUGH H. N/A
    I. LT. T.E. BOGGS, DET MO, DEPLOYED
    J. 149769
    K. AND L. N/A//
```

FROM: USS ARTHUR W RADFORD

Figure 5-3.-Sample Engineering Investigation (EI) Request.

The CAT I QDR (fig. 5-4) is submitted by routine precedence message within 2 working days after discovery of the deficiency (unless combined with an HMR/EMR). The CAT II QDR (figs. 5-5 and 5-6) is submitted on an standard form (SF) 368 within 5 working days after discovery of the deficiency to the CFA. Instructions on how to

prepare the CAT II QDR using SF 368 are listed below:

<u>Section I.</u> Section I is to be completed by the originating point as the information is applicable and available.

```
FROM: TRARON SEVEN SIX
      NAVAVNDEPOT NORTH ISLAND CA
       AIG FOUR TWO THREE
INFO: COMTRAWING SEVEN
       NAS MERIDIAN MS
UNCLAS //N04790//
SUBJ: CATIQUALITY DEFICIENCY REPORT
MSGID/GENADMIN/VT-76 QA//
REF/A/DOC/OPNAV/01JAN89//
AMPN/OPNAVINST 4790.2E//
RMKS/1. VT-76/34567
2. NAVAVNDEPOT NORIS
3. N34567-88-0012
4. 8068/NAS MERIDIAN MS
5. 1RD 2620-00-099-1848 SZ
6. TIRE
7. GOODYEAR 86896
8. 44319628
9. SER K339-5M-2
10. UNK
11. NEW
12. UNK
13. NO TIME
14. NO
15. A. REC'D 4
   B. INSP 4
   C. DEFICIENT 3
   D. IN STOCK 5
16. T-2C
17. UNK
18. N/A
19. YES
20. 13510
21. HOLDING 30 DAYS AT NAS MERIDIAN SUPPLY BLDG 601 PENDING DISPOSITION INSTRUCTIONS
22. A. TIRES REC'D FROM SUPPLY. INSPECTION REVEALED TIRES UNACCEPTABLE DUE TO SIDEWALLS
       BLISTERED ON TWO TIRES, BEAD SHOWS CRACKS ON ONE TIRE.
   B. DAMAGE TO A/C AND MAINTENANCE PERSONNEL
   C. NONE
   D. VISUAL INSPECTION/RECEIPT
   E. N/A
   F. THROUGH H. N/A
   1. AMSC P. T. JONES, LINE CPO, AUTOVON 564-3494
   J. THROUGH L. N/A//
```

Figure 5-4.-Sample Category I Quality Deficiency Report (CAT I QDR).

Item 1. From (Originating point). The originating point enters their address in block 1a, the name, duty phone, and signature of an individual who can serve as a contact for questions regarding the report in block 1b, and the date the report was signed and forwarded to the screening or action point in block 1c.


Item 2. To (Screening point). The originating point will complete the name of

screening point activity, the activity address code, address including zip code of the screening point where the report needs to be sent by the originator's activity in block 2a, the name, telephone number and signature of the individual who may serve as the screening point's point of contact in block 2b, and the date the person finished processing the report at the screening point in block 2c.

PRODUC	T QUALITY	DEFIC	IENCY REPO	RT		· · · · · · · · · · · · · · · · · · ·		CATE	3ORY I		CATEGORY II
1a. FROM (Or	iginator)					2a. TO (Screen	ing	Point)			
1b. NAME, TI	ELEPHONE NO	AND S	IGNATURE	1c. DA	TE	2b. NAME, TEL	EPH	ONE NO. A	ND SIGNATI	URE	2c. DATE
3. REPORT CO	ONTROL NO.		E DEFICIENCY COVERED	5. NAT	10N	AL STOCK NUMBE	R (N	ISN) 6. N	OMENCLAT	URE	
7a. MANUFA	.CTURE/CITY/S	TATE	7b. MFRS. CO	DE		7c. SHIPPER/CIT	Y/S	TATE		8. M	FRS. PART NO.
9. SERIAL/LO	T/BATCH NO.	10a. C	ONTRACT NO.	10b. PU	RCH	ASE ORDER NO.	100	C. REQUISIT	ION NO.	10d.	GBL NO.
11. ITEM NEW RI	EPAIRED/ VERHAULED		TE RECD., MFRE RED, OR OVERH			OPERATING TIME	AT		NMENT FUI	RNISH	IED MATERIAL
15. QUANTIT		a. RE	CEIVED	Ь.	INSPECTED	c.	DEFICIENT	•		d. IN STOCK	
16. DEFICIENT ITEM	a. END ITEM (AIRCRAFT, MOWER, ETC.)	(1) TY	PE/MODEL/SER	RIES							(2) SERIAL NO.
WORKS ON/WITH	b. NEXT HIGHER ASSEMBLY	(1) NA	TIONAL STOCK	NO. (N	SN)	(2) NOMENCLAT	URE		(3) PART N	0.	(4) SERIAL NO.
17. UNIT COS	T	18. ES	TIMATED REPA	AIR COS	ī	19a. ITEM UNDE		ARRANTY UN- KNOWN	19b. EXPI	RATIC	ON DATE
20. WORK U	NIT CODE/EIC (NAVYA	ND AIR FORCE	ONLY.)							
21. ACTION/I	DISPOSITION EXHIBIT FOR	D		ASED FO		RETURNED TO STOCK		SPOSED	EPAIRED		HER (EXPLAIN ITEM 22)
				ments	ances prior to difficulty. Continue on separate			ity, rause, actu	on take	n, including	
23. LOCATIO	ON OF DEFICIE	NT MAT	ERIAL								
24a. TO (Acti	on Point)					25a. TO (Support	Poi	nt) (Use Ite	ms 26 and 2	7 if m	ore than one)
24b. NAME,	TELEPHONE N	O. AND	SIGNATURE	24c DA	ATE	256 NAME, TELE	РНС	ONE NO. AN	ND SIGNATU	JRE	25c. DATE
26a. TO (Sup	port Point)					27a. TO (Support	Poi	nt)			
26b. NAME,	TELEPHONE N	O. AND	SIGNATURE	26c. DA	ATE	27b. NAME, TELE	РН	ONE NO. AI	ND SIGNATE	JRE	27c. DATE
NSN 7540-00	122 5541						_	STA	ANDARD FO	RM 3	68 (REV. 10-85)

Figure 5-5.-Sample Category II Quality Deficiency Report (CAT II QDR), Standard Form (SF) 368 (Front).

- Item 3. Enter the Report Control Number (RCN).
- Item 4. Date Deficiency Discovered. Enter the Julian date the deficiency discovered.
- Item 5. National Stock Number. Enter the national stock number of the deficient material.
- Item 6. Nomenclature. Enter the nomenclature of the material found to be deficient.
- Item 7. Enter the name/city/state of the manufacturer, maintenance contractor, or government activity that last repaired or overhauled the deficient item in block 7a, the manufacturers code in block 7b, and when the shipper of the item is different from the



*U.S. GPO 1986-496-360 STANDARD FORM 368 BACK (REV. 10-85)

Figure 5-6.-Sample Category II Quality Deficiency Report (CAT II QDR), Standard Form (SF) 368 (Back).

manufacturer, include the shipper's or supplier's name/city/state in block 7c.

Item 8. Manufacturer's Part Number. Self explanatory.

Item 9. Serial/Lot/Batch No. As applicable, enter the serial number, lot number, or batch number of the deficient material. Use item 22 if required.

Item 10. Enter the contract number in block 10a, the purchase order number in block 10b, the requisition number in block 10c, and the government bill of lading (GBL) number in block 10d.

Item 11. Item is New, Repaired, or Overhauled. Check the appropriate block to identify if the material is either new, repaired or overhauled.

Item 12. Date Manufactured, Repaired, or Overhauled. If the material is repaired or overhauled, enter the last repair or overhaul date.

Item 13. Enter operating time at failure (based on entry in block 12). Indicate the time material had been in service since new or since last repair, modification, or overhaul for rework material.

Item 14. Government Furnished Material. Government furnished material is any material that belongs to the government and is furnished to a contractor for some purpose. Check the appropriate block.

Item 15. Quantity. Quantity is a count of each individual item, disregarding unit of issue.

- a. Received. Enter the number of items received.
- b. Inspected. Enter the number of items inspected.
- Deficient. Enter the number of items that were determined to be deficient as a result of inspection.
- d. In Stock. Enter the number of items in stock, as applicable.

Item 16. Deficient Item Works On or With. Not applicable when reporting common/general type material received from supply but not installed or peculiar to a specific type of aircraft.

Item 17. Dollar Value of Deficient Items. Enter the dollar value of the material reported as being deficient, if known.

Item 18. Estimated Repair Cost. Enter the estimated cost and man-hours required to correct the discrepancy.

Item 19. Item Under Warranty. Check appropriate block in block 19a, and enter the expiration date of warranty in block 19b.

Item 20. Work Unit Code/Equipment Identification Code. Enter the most specific code available.

Item 21. Action or Disposition. Check one of the blocks to indicate the nature of the action taken or requested concerning the deficient material. If an exhibit is being held, indicate the number of days the exhibit will be held by completing the space provided (holding exhibit for XX days). If none of the blocks indicate the action or disposition taken or requested, check the other block and identify the nature of the action taken or requested in Item 22.

Item 22. Details. This item provides valuable information concerning the deficiency. For a fully comprehensive report, the following types of information should be entered in this item, if applicable and available:

- The requisition number under which the material was received.
- Describe how the safety of personnel or the activity mission is affected by the use of the defective item.
- Name of the activity that supplied the material.
 - Date of receipt.
 - Date of packaging.
- Explain what is wrong with the item or how it is different from an acceptable item to the best of the originator's ability. Explain how the item does not function with relating parts or assemblies, etc. Include specific violations of specifications, pertinent regulations, instructions, contracts, etc. Indicate if an exhibit is being held.

- How deficiency was detected or confirmed; i.e., visual inspection, functional operation, etc.
- Include the number of previous known deficiencies concerning these items.
- Where the deficiency condition was discovered; that is, receipt inspection, during cyclical inspection, during maintenance, special inspection directed by inventory control point, etc.
- Include storage and/or handling information when it appears that these factors have contributed to the deficiency being reported.
- List the supporting documents included whenever possible. When photographs are taken, a 12-inch or other ruler should be used and a scale placed alongside the object, which should appear in each photograph. Measurements should also be shown on sketches.

<u>Section II.</u> Section II is to be completed by the action and support point, as applicable.

Item 23. Location of Deficient Material. Address and location where the exhibit is being held.

Item 24. To (Action Point). A focal point, identified within each component of the Armed Services, responsible for the resolution of a reported product quality deficiency, including necessary collaboration with support points. The screening point will enter the name and address of the action point to which the report is being submitted in block 24a; the action point will enter the name, duty phone, and signature of the individual who may serve as the action point's point of contact in block 24b; and the date the report was signed by the individual identified in block 24b is entered in block 24c.

Item 25. To (Support Point). An activity, for example, Naval Aviation Depot Operations Center (NAVAVNDEPOTOPSCEN), commercial rework activity, procurement contracting office, Naval Aviation Depot (NAVAVNDEPOT), Naval Plant Representative Office (NAVPRO), or local engineering support office, that assists the action point, when requested, by conducting and providing results of a special analysis or investigation pertinent to correction and prevention of a reported deficiency is entered in block 25a (if more than one support point is

involved, items 26 and 27 should be used). The name, telephone number, and signature of the individual who may serve as the support point's point of contact is entered in block 25b, and the date the report was signed by the individual identified in block 25b is entered in block 25c.

Items 26a and 27a. These blocks are used to address the reply from the action point to additional screening point (s).

Items 26b and 27b. Name, telephone number, and signature: The additional support point(s) will enter the name(s), duty phone number(s), and signature of the individual(s) who may serve as the support point's point of contact.

Items 26c and 27c. Date: Enter date(s) the report was signed by the individual(s) in block 26b and 27b.

Item 28. Findings and Recommendations of Investigation:. The final reply will include the following:

- The findings of the investigation conducted.
- Disposition instructions for deficient material, when appropriate.
- Need for alert notifications or field fix bulletins, if applicable.
- A comment regarding allowance for credit or no credit for the material reported as deficient, if applicable.
- When appropriate, provide other screening points of known military users with the results of the investigation and the corrective actions.

Item 29. Action Taken: Explain what corrective action was taken to preclude recurrence.

Item 30. Results of Depot Surveillance: Show results of depot surveillance and planned action; for example, replacement or repair by contractor, disposal, or issue.

AIRCRAFT DISCREPANCY REPORT (ADR)

This report provides a direct method for reporting minor, major and/or critical

discrepancies in quality assurance procedures to aircraft manufacturers, NAVAVNDEPOTs, and other activities performing maintenance on aircraft. This method of reporting is not used in lieu of the NAMDRP; it compliments the program. It simply highlights areas in immediate need of attention to ensure a more acceptable standard of quality in aircraft maintenance and rework procedures.

Effective use of SF 368 in initiating corrective or preventative action is dependent upon a clear description of discrepancies and corrective actions taken to identify the problem and the parts involved to permit objective analysis of each discrepancy. (Figures 5-7 and 5-8 show a sample ADR using SF 368).

Equipment shortages, ferry or shipping damages, deterioration during pool storage, or

PRODUC	T QUALITY	DEFIC	ENCY REPO	RT				CAT	EGORY I		CATEGORY II
1a. FROM (Or HSL THRE NAS NORI	•	5593				2a. TO (Screeni NAVAL AVI PATUXENT	ATIC	N DEPOT	PERATIONS CE 70-5449	ENTER	NADOC 4101
1b. NAME, TE	LEPHONE NO	AND S	GNATURE	1c. DA	TE	2b. NAME, TELE	РН	ONE NO.	AND SIGNAT	URE	2c. DATE
CDR D. POTTER	, AV 356-4692, CO	M. (301)-X	G3 4692	29 Ja	n 87	JACK JONES, AV	356-	4692, COM.	(301)-863-4692		
3. REPORT CO V68626-87		DISC	E DEFICIENCY OVERED	i	TION,	AL STOCK NUMBER	R (N	ISN) 6.	NOMENCLAT		ANCY REPORT
	CTURE/CITY/S		7b. MFRS. CO			7c. SHIPPER/CIT	Y/S	TATE			FRS. PART NO.
	TATIONAL/DOTH		N/A			N/A					N/A
9. SERIAL/LO	T/BATCH NO.		ONTRACT NO. 7-86-C-9006	10b. PU	JRCH.	ASE ORDER NO.	100	C. REQUIS	ITION NO.	10d	GBL NO.
11. ITEM	PAIRED/	12. DA	TE RECD., MFR		13.0	PERATING TIME A	L		RNMENT FU	RNISH	IED MATERIAL
	/ERHAULED		20 JAN 87			N/A				t	UA.
		a. RE	CEIVED		Ь.	INSPECTED	c.	DEFICIE	NT		d. IN STOCK
15. QUANTIT	Y	N/A	٨.			N/A		N/A			N/A
16. DEFICIENT	a. END ITEM (AIRCRAFT, MOWER, ETC.)	(1) TY	PE/MODEL/SE	RIES	L		.	. —		*	(2) SERIAL NO. 152191
WORKS ON/WITH	b. NEXT HIGHER ASSEMBLY	' '	TIONAL STOCI	(NO. (N	ISN)	(2) NOMENCLAT	URE		(3) PART N	0.	(4) SERIAL NO.
17. UNIT COS		18. ES	TIMATED REP	AIR COS	Ť	19a. ITEM UNDE □ YES □NO		ARRANT	Ү 196. ЕХРІ	RATIO	ON DATE
20. WORK U	NIT CODE/EIC	NAVY	ND AIR FORCE	ONLY.)	N/A					
21. ACTION/0	DISPOSITION EXHIBIT FOR			ASED F	-	RETURNED TO STOCK		SPOSED	REPAIRED		THER (EXPLAIN ITEM 22)
22 DETAILS	Describe, to best a	bility, who	it is wrong, how an	d why, cin	rumsta	nces prior to difficulty,	lescr	iption of diff	iculty, cause, act	on take	en, including
	TANCE OF AIRC		act copies of suppo	reing duct	menue	. Continue on separate	Ī	IPL	E		
REP		UMBER			AZIM	UTH LOWER LINK (W				UED.	
2. MAJ MOI			ASER GEARBOX (B. 71 MAN-HOUR		UC 26:	221) CORRODED BEYO	ND	LIMITS AK	OUND TOP CHI	PDETE	CTOR
3. MIN	OR: NO WEIG	HT AND	BALANCE ENTRY	FOR AF	C's 243	, 223, 235, 236, and 239	. EN	TRIES MAI	DE. 1.2 MAN-HO	URS	
23. LOCATIO	ON OF DEFICIE	TAM TV	ERIAL	N/A							
24a. TO (Act	ion Point)	HAYE	PRO HAYES S INTERNATION AN, AL 36301	AL CORP.		25a. TO (Support NAVAL AV NAS PENSA	IATI	ON DEPOT	(Q&RA)	27 if r	nore than one)
24b. NAME,	TELEPHONE N	O. AND	SIGNATURE	24c. D	ATE	25b. NAME, TELE	PH	ONE NO.	AND SIGNAT	URE	25c DATE
26a. TO (Sup	port Point)					27a. TO (Support					
			NAS NORFOLK,	T			_		2) NAS NORFOL		
26b. NAME,	TELEPHONE N	O. AND	SIGNATURE	26c. D	ATE	276, NAME, TELE	PH	ONE NO.	AND SIGNAT	URE	27c. DATE
NSN 7540-00	122 5541					<u> </u>			TANDARD F	ORM	368 (REV. 10-85)

Figure 5-7.-Sample Aircraft Discrepancy Report (ADR), Standard Form (SF) 368 (Front).

28. FINDINGS AND RECOMMENDATIONS OF INVESTIGATION. (Explain in detail. Continue on separate sheet of paper, if necessary.) SAMPLE 29. ACTION TAKEN 30. RESULTS OF DEPOT SURVEILLANCE INSTRUCTIONS and received in Block 12, if available. 1a. FROM (Originator) - Complete name of activity (no acronyms when sending deliciency report across component lines), activity address code 13. OPERATING TIME AT FAILURE - Time item had been in operation since new, overhauled, or repaired when the deficiency was discovered, citing the (ACC), address including zip code of the activity originating the report 1b. NAME, TELEPHONE NO., AND SIGNATURE: Provide name, telephone no., (include all available telephone numbers; FTS; Autovon, and commercial) and signature of an individual who can serve as a contact for questions appropriate performance element (miles, cycles, hours, etc.). 15c. QUANTITY DEFICIENT - Enter the quantity found deficient of those regarding the report and/or to request exhibits or samples 15d. QUANTITY IN STOCK - Enter the quantity of material from the same 1c. DATE - Enter date report was signed and forwarded to the screening or manufacturer remaining in stock. 2a. TO (Screening Point) - The originating point will complete name of the screening point activity (no acronyms when deficiency report will be sent across component lines), the activity address code (AAC), address including approach of screening point where the report needs to be sent by the originator's activity. For those activities that do not have screening points, 17. UNIT COST - Dollar value of deficient item when known. Not applicable on reporting vehicles to GSA. 18. ESTIMATED REPAIR COST - Unit cost times number of units for replacement or estimated repair costs (including overhead) times number of units for correcting all the deficient items reported when it can readily be determined. Not applicable on reporting vehicles to GSA 2c. DATE - Enter the date the person finished processing the report at the 19. ITEM UNDER WARRANTY - Check if item is known to be covered by contractor warranty. If yes provide expiration date. 3. REPORT CONTROL NUMBER - Number assigned to report when a numbering system is used. Those activities which are reporting quality deficiencies across component lines and are to comply with the DLA 21. <u>ACTION/DISPOSITION</u> - A check in the appropriate block to indicate the action taken or requested. When an exhibit or sample is being held, indicate Regulation 4155.24 should reference the report control number as prescribed in the regulation. the number of days in the space provided. (An exhibit or sample shall be held the number of days in the space provided. (An exhibit or sample shall be need for a minimum of 30 calendar days from date the report is transmitted to the action point. Reporting activities are reminded that the packaging, packing and shipping containers are to be held along with the exhibits to facilitate investigation.) When none of the items indicate the actions or disposition taken or requested, check "Other" and identify the nature of action taken or 7a. MANUFACTURER:CITY/STATE - Name of the manufacturer, the maintenance contractor, or Government activity which last repaired or overhauled the deficient item. For motor vehicles or components thereof, requested in item 22 enter name of manufacturer of the vehicle or component, as appropriate 7b. MANUFACTURER'S CODE - Code of the manufacturer as listed in cataloging Handbook H4.1 (Name to code), Federal Supply Code for 23. LOCATION OF DEFICIENT MATERIAL - Address and location of deficient Manufacturers (United States and Canada). 24a. <u>TO (Action Point)</u> - Name, in the clear address, including 21p code of the action point to which the report is being submitted. 7c. SHIPPER/CITY/STATE - When the shipper of an item is different from the manufacturer, also include the shipper's or supplier's name 24c. <u>DATE</u> - Enter the date the report was forwarded to an action point or the date the findings and recommendations were completed. 9. SERIAL/LOT/BATCH NO. - Manufacturer's serial, lot, or batch, number of 28 FINDINGS AND RECOMMENDATIONS OF INVESTIGATION - Include the 10. CONTRACT; PURCHASE ORDER; REQUISITION; GOVERNMENT BILL OF LADING (GBL) NO. • Enter these numbers or any other available transportation document number in lieu of the GBL. Such numbers appear on the container, purchase document and/or the item. It is extremely helpful findings and recommendations for resolution of complaint. 29 - ACTION TAKEN - State the action taken to resolve the complaint if these items are furnished when the material was supplied by GSA 30. RESULTS OF DEPOT SURVEILLANCE - Show results of depot surveillance and planned action (i.e., replacement or repair by contractor, disposal, issue,

Figure 5-8.-Sample Aircraft Discrepancy Report (ADR), Standard Form (SF) 368 (Back).

etc.)

STANDARD FORM 368 BACK (REV. 10-85)

11. ITEM - Check the appropriate block; provide the dates manufactured

*U.S. GPO: 1986-496-360

other discrepancies that do not directly pertain to the quality of rework or manufacture are not reported by the reporting custodian. ADRs should not include discrepancies that are not a part of the negotiated work package of rework or specification.

An acceptance inspection is performed as soon as possible after the aircraft is delivered and prior to maintenance (other than required to complete the acceptance inspection) or further flight. Only those discrepancies noted by the pilot/ferry crew and those found during the acceptance inspection are reported.

Discrepancies discovered during the initial acceptance inspection of aircraft received from a contractor as newly manufactured and those reworked by a Navy, commercial, or interservice activity are reported as an ADR on the SF 368. If no deficiencies are found during the acceptance inspection, a negative report will be submitted stating, "No discrepancies noted. Reply not required."

The cognizant naval plant representative officer or other administrating contract officer/NAVAVNDEPOT encloses sufficient copies of the SF 368 with envelopes appropriately preaddressed in each aircraft logbook for delivery with the aircraft. For the most part, completion of the SF 368 is self-explanatory. A report control number is assigned to each report. Each report control number commences with 0001 at the beginning of each calendar year and progresses consecutively throughout the year.

A report is required on each newly reworked aircraft received. It should be completed as soon as possible after completion of the aircraft acceptance inspection, but in no case prepared later than 30 days after receipt of the aircraft.

The discrepancies that are entered on the report are usually furnished to QA by personnel in the production divisions. If the space for reporting discrepancies on one form is insufficient, a separate sheet of paper is issued.

The report is used to report critical, major, and minor discrepancies found by the using activity on aircraft received from a contractor or a rework activity as well as to evaluate

the rework activity's quality control system. Critical, major and minor discrepancies are defined as follows:

<u>Defect, Critical.</u> A defect that constitutes a hazardous or unsafe condition, thus making the aircraft unsafe for flight or endangering operating personnel.

<u>Defect, Major.</u> A defect, other than critical that could result in failure or materially reduce the usability of the unit or part for its intended purpose.

<u>Defect</u>, <u>Minor</u>. A defect that is not likely to reduce materially the usability of the unit or part for its intended purpose.

After completion, the original report is forwarded to the aircraft manufacturer (in case of new aircraft) or to the NAVAVNDEPOT/commercial rework activities.

A copy of each report is forwarded to the controlling custodian, the cognizant commander, fleet air functional wing, and the cognizant NAVAVNDEPOT. For newly manufactured aircraft, a copy is forwarded to the contract administration office (CAO) and to the Commander, Naval Air Systems Command. For aircraft reworked at NAVAVNDEPOT, a copy is forwarded to Naval Aviation Depot Operations Center (NAVAVNDEPOTOPSCEN). For aircraft commercially reworked, a copy is forwarded to CAO and to Naval Aviation Depot Operations Center (NAVAVNDEPOTOPSCEN).

TECHNICAL PUBLICATION DEFICIENCY REPORT (TPDR)

Occasionally, the AZ working as publications librarian will discover deficiencies in publications. More often, deficiencies will be discovered by personnel who are or have been using the technical publications. In such cases, the technical librarian should report the deficiency in accordance with the information discussed below.

This report provides a simplified procedure for reporting technical publication safety hazards and routine deficiencies. There are two different categories for reporting technical publication deficiencies that are explained below:

<u>CAT I TPDR.</u> This report is submitted by using the CAT I TPDR message format (fig. 5-9) when a technical publication deficiency is detected

LAST LOOP - VICE "FF" THREAD.

THE ABOVE RECOMMENDATIONS.

N. PRCS BEALL, AV/EG BRANCH SUPERVISOR, DEPLOYED//.

that, if not corrected, could result in death or injury to personnel or damage to or loss of aircraft, equipment, or facilities. The importance of submitting a message as soon as possible for these types of deficiencies is strongly emphasized.

FROM: USS MIDWAY NAVAIRTECHSERVFAC PHILADELPHIA PA TO: NAVWPNCEN CHINA LAKE CA AIG FOUR TWO THREE COMFAIRWESTPAC ATSUGIJA COMLATWINGPAC LEMOORE CA UNCLAS //N04790// SUBJ: CAT I TECHNICAL PUBLICATION DEFICIENCY REPORT MSGID/GENADMIN/AIMD// REF/A/DOC/OPNAV/01JAN89// REF/B/DOC/NAVAIR/15FEB83// NARR/REF A IS OPNAVINST 4790.2E, REF B IS NAVAIR 13-1-6.2 BASIC DTD 15 FEB 83/RAC 69 DTD 1 FEB 85// RMKS/1. USS MIDWAY (CV-41)/03341 NAVWPNCEN CHINA LAKE CA R03341-88-0017 8187/USS MIDWAY 0513-LP-000-2150 6. THROUGH 21. N/A 22. A. NA 13-1-6.2 B. NES-12 PARACHUTE ASSY C. 15 FEB 1983 D. RAC 69 DTD 1 FEB 1985 E. N/A F. 15-12c G. 15-18a-14 H. 15-12c I.THROUGH K. N/A L. ASSEMBLY INDUCTED INTO AIMD FOR SCHEDULED REPACK AND USE AS A TRAINING AID DURING A LECTURE GIVEN BY AIMD PARALOFT PERSONNEL TO CVW-5 A-7E PILOTS DURING A SAFETY STAND-DOWN. DURING EXPLANATION AND ACTIVATION OF THE FOUR-LINE RELEASE SYSTEM, THE "DAISY CHAIN" SECURING LINES I AND 2 FAILED TO UNCHAIN. INVESTIGATION REVEALED THAT THE "FF" THREAD ENTERS AND EXITS THE FLUTE TOO CLOSELY, THE INDIVIDUAL THREADS OF THE FLUTE WEBBING WILL BREAK INSTEAD OF THE "FF" THREAD. IF THE LAST LOOP OF THE "DAISY CHAIN" IS NOT PULLED INTO THE FLUTE TO POSITION IT DIRECTLY UNDER THE ENTRY AND EXIT POINTS OF THE "FF" THREAD IN THE FLUTE, THE THREAD WILL BREAK BUT COULD BE PULLED THROUGH THE FLUTE WEBBING AND BE OF SUFFICIENT LENGTH TO BECOME ENTANGLED IN THE "DAISY CHAIN". THIS COULD CAUSE A "LOCKING" OF THE REMAINING "DAISY CHAIN" AS IT DID IN THIS CASE. IF THE "FF" THREAD DOES NOT PIERCE THE LANYARD THROUGH THE CENTER, BUT ONLY CALCHES A PORTION OF THE OUTER CASING, IT IS POSSIBLE TO RUPTURE THE OUTER CASING OF THE LANYARD AND FAIL TO BREAK THE "FF" THREAD TACKING. PHOTOGRAPHS ARE AVAILABLE UPON REQUEST. M. RECOMMENDATIONS: (1) RECOMMEND FOLLOWING WARNING BE INSERTED BETWEEN STEPS 13 AND 14 OF PARA, 15-18A OF REF B: "WARNING" ENSURE THAT ENTRY AND EXIT POINTS OF THE "FF" THREAD ARE AT LEAST 1/4 INCH APART. ENSURE THAT THE LAST LOOP OF THE "DAISY CHAIN" IS PULLED FAR ENOUGH INTO THE FLUTE TO POSITION IT DIRECTLY BENEATH THE ENTRY AND EXIT POINTS OF THE "FF" THREAD. (2) RECOMMEND THAT FIG 15-12C BE CHANGED TO SHOW EMPHASIS ON SEPARATION OF ENTRY AND EXIT POINTS OF THE "FF" THREAD AND POSITIONING OF THE LAST LOOP. (3) RECOMMEND THAT ONE TURN OF WAXED NYLON "E" THREAD, SINGLE, BE USED TO SECURE THE

Figure 5-9.-Sample Category I (CAT I) Technical Publication Deficiency Report Message.

(4) RECOMMEND THAT ALL ASSEMBLIES HAVING ACC 383 INCORPORATED BE CHANGED TO REFLECT

CAT II TPDR. This report is submitted using the Technical Publication Deficiency Report, OPNAV 4790/66 (figs. 5-10 and 5-11), when technical publication deficiencies include technical errors, wrong measurement values, incorrect use of support equipment, wrong sequence of adjustments, part number errors or omissions.

Technical publications include maintenance requirements cards (MRCs), checklists, work unit

code (WUC) manuals, shop process cards, maintenance instruction manuals (MIMs), weapons and stores loading manuals, conventional and nuclear weapon checklists, stores reliability cards, illustrated parts breakdowns (IPBs), technical directives (TDs), and technical manuals. The TPDR is not applicable when reporting deficiencies in instructions or notices. Deficiencies in NATOPS manuals should be

	Т	ECHNICAL I	PUBLICA	ATIONS	DEFICI	ENCY REPO	RT		
NAVAIR	TECHSERVE	AC USE ONLY	a. Q.	A SEQUENCE	NO.	b. DATA MANAG	ER CODE	c. CFA	PRIME CODE
I, REPORTING ACTIV	/ITY		2. Rí	EPORT CONTR	OL NUMBER			•	
			3. RI (YRN	EPORT DATE	4 WEAPON	SYSTEM ON			5. DISCREPANCY CODE
6. TECHNICAL MANU	JAL NUMBER			7. TECH. MA	AN. DATE	8	CHG. NO.	& DATE	9. W/P NO
10. SEC/PG NO.	11. PARA NO.	12. FIG/TBL	NO	13.	CART. NO.	. 14. CART.	DATE	1	I5. FRAME NO.
16. DEFICIENCY	IONS		SA	AMP	LE				
18. IMPACT									
19. MEDIA EVALUA	TED: (Only one che	ck block is required pe	r item.) PAPER & FILM		·				
REMARKS 20 REPORTED BY (F	Name, rank/rate)		ΑU	TOVON	21. RELEASED	BY (Name, rankirate)		AUTOVON
OPNAV 4790/66 (REV	. 5-88)		S/N 0107-LF-	002-4400		11	NSTRUCT	IONS C	N REVERSE SIDE

Figure 5-10.-Sample Category II (CAT II) Technical Publication Deficiency Report (OPNAV 4790/66) (Front).

reported in accordance with the latest edition of NAVAIR Instruction 3510.1 or OPNAV Instruction 3500.22.

All activities must submit CAT I TPDR priority messages within 24 hours of discovery of a deficiency. The action addressee for the message report will be the cognizant field activity (CFA) of the equipment, if known, and Naval Air Technical Services Facility (NAVAIRTECHSERVFAC), Code 40.

All activities must submit CAT II routine technical publication deficiencies using OPNAV 4790/66. The original and one copy are sent to NAVAIRTECHSERVFAC, Code 40, and one copy is sent to the CFA of the equipment, if known. A copy is retained by the originating activity for record purposes.

NAVAIRTECHSERVFAC will serve as the central manager for all NAVAIRSYSCOM

INSTRUCTIONS

- FROM: (Reporting Activity.) The Reporting Activity will enter complete mailing address.
- REPORT CONTROL NUMBER: Enter the Report Control Number (RCN).
- 3. REPORT DATE: This identifies the year, month, and the day that the report was prepared, and consists of six digits. The date 15 June 1989 would be presented in the following format: 890615. The first two digits indicating the year (89), the second two digits indicate the month (06), and the remaining two digits specify the day (15).
- WEAPON SYSTEM APPLICATION: Give the specific weapon system against which the deficiency is detected.
- DISCREPANCY CODE: This is a numeric code used to describe the type of discrepancy found in the technical publication being reported deficient. A complete list of codes are as follows:
 - 1. Typographical Errors
 - 2. Incorrect Procedures
 - 3. Schematic Errors
 - 4. Part Number Errors 5. SM&R Code Errors SAMPLE
 - 6. Illustration Errors
 - 7. Incorrect Values/Tolerances
 - 8. Incorrect References
 - 9. Safety (Cautions & Warnings)
 - 10. Indexing problems
 - 11. Illegible
 - 12. Print Error (Head to Toe or information cut off)
 - 13. Missing/Improperly Collated Pages
 - 14. Film Density
 - Cartridge Loading (Wrong Film, Cartridge Indexing, No Film, and Inverted Loading)
 - 16. Other
- TECHNICAL MANUAL NUMBER: Give the complete NAVAIR number assigned to the manual being reported as deficient. Only one Technical Manual should be reported per TPDR.
- TECHNICAL MANUAL DATE: This date appears on the bottom right hand corner of the title page. The date shall be presented in

- the format described in Item 3.
- CHANGE NUMBER AND DATE: This appears directly under the basic date of the manual on which the deficiency is located. Present date in same format as item 3.
- WORK PACKAGE NUMBER: Enter the number in which the deficiency is located.
- SECTION/PAGE NUMBER: Enter the number of the page of the technical manual on which the deficiency is located.
- 11. PARAGRAPH NUMBER: Enter the specific number in which the deficiency is located.
- **12. FIGURE/TABLE:** Enter when an illustration or table is involved in the deficiency.
- 13. CARTRIDGE NUMBER: Enter the number being reported deficient.
- 14. CARTRIDGE DATE: The date shall be presented in the format described in Item 3.
- 15. FRAME NUMBER: Enter the frame number of the cartridge on which the deficiency is located.
- 16. DEFICIENCY: Be very specific. Provide complete information regarding discrepancy, including drawings, schematics, sketches, and references. If necessary, attach copies.
- 17. RECOMMENDATION: Be very specific. Provide complete information regarding the corrective action required, including drawings, schematics, sketches, and references. If necessary, attach copies.
- IMPACT: Enter concise statement of the impact of this discrepancy on work load/ operational readiness.
- MEDIA EVALUATED: Check applicable block for media that is being reported deficient.
- 20. REPORTED BY: Give name, rate/rank, and autovon number of person reporting deficiency to ensure receipt by reporter of notification of action taken.
- 21. RELEASED BY: Name, rank/rate, title, and autovon number of releasing official.

MAIL ORIGINAL AND 1 COPY TO:

Commanding Officer, Naval Air Technical Services Facility, Quality Assurance Dept (40) 700 Robbins Ave., Phila., PA 19111-5097

COPY TO COGNIZANT FIELD ACTIVITY

OPNAV 4790:66 (REV. 5-88) (BACK)

Figure 5-11 .- Sample Category II (CAT II) Technical Publication Deficiency Report (OPNAV 4790/66) (Back).

technical publications and will ensure the following:

- Maintain a record of all technical manual deficiencies.
- Acknowledge receipt of each TPDR to the originator and assign CFA action for TPDRs as required. This will be accomplished within 1 working day after receipt of CAT I TPDRs, and within 10 working days after receipt of CAT II TPDRs.
- Coordinate action with CFA and contractor to ensure correction of technical publications.
- Follow-up on each TPDR to ensure corrective action is accomplished.
- Provide TPDR status as required to the ACC/TYCOM.

When the TPDR has been completed, it should be passed on to the librarian's supervisor. The report receives a preliminary review by the supervisor, who, in turn, forwards it into the proper channels for further processing. Further processing normally involves additional review and checking, signing by the quality assurance officer or designated representative, and mailing.

The file copy retained by the librarian provides a means of checking reissues and changes. When reissues or changes to publications, in which discrepancies have been reported, are received in the library, the librarian should check to see if all discrepancies reported by the activity have been corrected. When a reissue contains errors or omissions previously reported, they should be reported again.

A simple method that may be used for checking for outstanding discrepancies requires each publication reported on to be flagged with a colored marker or otherwise identified in a conspicuous place on the front cover. Whenever a flagged or marked publication is replaced by a reissue, it is a simple matter to pull all the TPDR copies pertaining to that publication and check the new issue for the same errors. If all are not correct, new report copies should replace the old ones in the file. In this case, the flag should be transferred to the new basic publication.

DATA ANALYSIS

To obtain more efficient use of information collected by the maintenance data system (MDS), and to increase the effectiveness of the quality assurance program, a qualified data analyst is assigned to the QA/A division. The data analyst must be a senior petty officer formally trained in MDS procedures, data processing, and statistical analysis.

As an AZ3 or AZ2, you will not normally be assigned the duty of data analyst; however, depending on the size of the activity, you might be assigned to assist in the data analyst responsibilities. You will need to have a working knowledge of the responsibilities assigned to the analyst (which were discussed in chapter 1) and become familiar with the MDS reports used by the data analyst to examine and extract important data, which may significantly impact the maintenance effort of your command.

ANALYSIS TECHNIQUES

Analysis techniques include the extraction, examination, and presentation of pertinent data. The resulting analysis products will assist management in attaining effective and economical use of personnel and material resources. The MDS is designed to accumulate factual data pertaining to all phases of maintenance. This data is made available to management in the form of standard MDS reports. The function of analysis is to examine the data contained in these reports and determine what affect the conditions indicated may have on the maintenance effort. Analysis will show favorable and unfavorable conditions in the maintenance plan. The MDS will be of little value if its data is not used to the fullest extent.

Initiation of Analysis

The requirements for analysis may come from various sources and apply to a wide range of maintenance subjects. Analysis may be initiated to provide an answer to a specific problem, or to study selected areas of maintenance, for example, personnel utilization and productivity of work centers. The requirement for analysis should be the result of a "need to know" situation imposed by management. An analysis based on clear, concise requirements is more likely to be meaningful and useful to the maintenance manager than one based on generalities.

Data Selection

Once the subject of the analysis has been identified, the analyst must determine what data will be needed to fulfill the requirement. No standard rules can be applied to this phase of analysis. The analyst must choose wisely, ensuring all facts that have a bearing on the subject are included in the analysis. The analyst must also know which report, or combination of reports, will best provide the needed data.

Data Extraction

The extraction of data is usually a mechanical process; certain columns or lines of the report are screened to identify and select the desired data. Selected data are transposed to some type of work sheet to aid in subsequent steps of the analysis. Design of the work sheet should be simple, allow posting of extracted data in a methodical sequence, and provide space for the computation of totals and subtotals as needed.

Translation of Data

The major portion of the extracted data consists of coded entries, which must be translated into meaningful terms before being analyzed. The design of the work sheet should incorporate translation provisions; for example, columnar headings can contain both coded and descriptive information.

Examination of Data

This process involves the detailed study or examination of all of the data. There is no restriction as to who may do an analysis. In many instances it is desirable that an analysis be completed by a person technically qualified in the subject, although this is not always possible. Identical results may often be obtained through teamwork. For example, personnel assigned to QA/A may accumulate the required data, call in a representative from a work center to examine the data, and jointly prepare a report pertinent to the analysis. Regardless of who accomplished the examination, the intent of the detailed study of the data is the same; that is, (1) to determine if a problem actually exists, (2) to identify the factors contributing to the problem, (3) to list possible conclusions, and (4) to suggest possible alternative courses of action.

SUBMISSION OF SOURCE DOCUMENTS TO THE DATA SERVICE FACILITY

Two copies of the document control form (DCF) (fig. 5-12) are prepared each time the reporting activity submits source documents to the data services facility (DSF).

The documents to be submitted are separated, grouped, and counted. The submitting activity enters, in the appropriate line under Forms Count column 1, the number of documents submitted of that category. The DSF will enter the Julian date and time received, signature, and verify the number of documents by entering their count of the document in the Forms Count column 2,

If, during DSF processing, a document is found to be illegible or otherwise cannot be entered, it is returned to the submitting activity for correction. The questionable data elements are circled in red by the DSF. A total of these rejected documents are entered in the forms reject column. Rejected or late documents submitted after the end of an accounting period must be submitted with a separate document control form (DCF). This data will be processed with the next accounting period data. NALCOMIS is a dedicated automatic data processing (ADP) system and precludes the use of DCFs. Refer to the NALCOMLS User's Manual for processing requirements.

LOCAL DATA BASE CORRECTION PROCEDURES

To ensure that your Maintenance Data System (MDS) reports reflect accurate information, you will need to make corrections to MDS source documents that are in error. To discuss every correction procedure for MDS source documents in this chapter would be impossible, but we will discuss the basic correction procedures. For more information concerning local data base correction procedures, you should refer to the latest edition of OPNAVINST 4790.2. Those activities using NALCOMIS refer to the NALCOMIS User's Manual for specific details of local data base correction procedures.

Reporting activities will submit source documents daily to their DSF for processing. The DSF will enter data from source documents and produce daily audit reports (DARs). If problems are encountered during the data entry, the DSF circles the data element in red that cannot be

entered; for example, blanks, excessive characters, or illegible entries. The source document is then returned to the submitting activity for correction and resubmission. To the maximum extent possible, local inputs and data base errors should be corrected daily, as they are identified.

Data elements on the record part I or part II of the DAR that are found to be in error will be lined out with a single red line. The correct data will be handscribed immediately above the lined

out entry and "C" entered under the Correction Code (CC) column on the far right side of the record to be corrected. If the data to be corrected is in the VIDS/MAF A-Z record, "C" will be entered immediately to the left of the letter prefix of the VID/MAF record requiring correction.

If a whole record/source document is to be deleted, a "D" will be recorded directly under the CC column on the far right side of the record or immediately to the left of the letter prefix in the

DOCUMENT CONT	KUL	FUK	IVI	2. JULIAN DATE			
ORGANIZATION				3. AWAY FROM HOME CODE			
				4. SUPPLY ORGANIZATION CODE			
CARDS/FORMS BY TYPE	FORMS	COUNT.	FORM REJECT	CARDS/FORMS BY TYPE	FORMS	OUNT 2	FORM REJEC
5. MDR FORMS				9. LOCAL CONTROL			
SUPPORT ACTION FORM				a. DAILY AUDIT PART I			
VIDS MAF (COPY 1)				b. DAILY AUDIT PART II	ļ		
SAF REPLENISHMENT		ļ		c DAILY AUDIT PART III			<u> </u>
VIDS/MAF (CLOSEOUT)	ļ				_		<u> </u>
METER CARD (GREEN COPY)	ļ						_
METER CARD (GREEN COPY) (CLOSEOUT)	ļ				<u> </u>		<u> </u>
	ļ						_
6. TRAINING DEVICE FORMS							
UTILIZATION				10. COMMENTS/LOCAL USE			
	1						
<u> </u>	1						
······································		<u> </u>					
7. FLIGHT DATA FORMS							
NAVAL AIRCRAFT FLIGHT RECORD	+			Í			
	+	†	 				
	+	-	-				
8. MATERIAL REPORTING	<i>10000000</i>	300000					
VIDS MAF (COPY 2)	-	 		{			
. DD 1348	-	<u> </u>		11. JULIAN DATE/TIME RECEIVED			
				John Onle Mile Bechieb			
		ĺ		12. RECEIVED BY (Signature)			

Figure 5-12.-Document Control Form (DCF) (OPNAV 4790/45).

case of the VIDS/MAF copy 1 or METER card (green copy) A-Z records.

MAINTENANCE DATA SYSTEM (MDS) REPORTS

Within the Maintenance Data System (MDS), large amounts of readiness and maintenance data are generated at the local level. This data consists of coded elements that are summarized in daily and monthly reports. The description, content and use of the MDS reports prepared by the DSF and used by the data analyst (at the organizational level) are discussed in this section of the TRAMAN. NAVFLIRS reports were previously discussed in chapter 4 and will not be discussed in this chapter. Those activities using NALCOMIS should refer to *NALCOMIS User's Manual* for information concerning the Maintenance Data System (MDS).

VIDS/MAF COPY 1 DAILY AUDIT REPORT (DAR)

VIDS/MAF COPY 2

This report is prepared from data submitted on copy 1 of the VIDS/MAF and is printed in three parts. Part I contains data that has no errors and is considered valid. Part II contains records submitted during the current reporting period which contain errors that have not been corrected.

Part III will be printed if there are any correction/deletion records which cannot be applied to the local data base due to erroneous data. The work center supervisor should verify the daily audit report (fig. 5-1 3) to ensure that all data contained on the work centers VIDS/MAFs have been correctly key punched by the DSF.

MONTHLY PRODUCTION REPORT (MDR-2)

This report lists all maintenance actions in work center sequence including technical directive compliance and data entered in the (H-Z) Failed/Required Material block of the VIDS/MAF (fig. 5-14). It also provides the work center supervisor with statistical data pertaining to the work center; for example, man-hours expended to repair a subsystem.

JOB CONTROL NUMBER (JCN) CONSOLIDATION REPORT (MDR-3)

This report is a consolidated list, by organization, of all maintenance and technical directive compliance actions submitted during the month by the parent organization and the supporting activity. This report is prepared from data submitted on the VIDS/MAF copy 1 for all transaction codes except 00, 02, and 03 (fig. 5-15).

30 JAN 89

										M	SUP		****J(N	*****	SUP		DOC	REC	
wuc ı	TEC 8	MFGR 12	ORG 27	NSNPN 30	UI 45	QTY 47			C 52		DAT 54		DAY 64			ORG 75	AWAY 78		TYP	-
7462512	AFP8	97942	A9D	41300078859649F	EA	01	2R	w	A	н	9028	AJī	020	361	AA	A8D		0290012	61	
74325	AFPB	97942	A9D	1439006777586BF	ΕA	01	2R	W	A	Н	9028	AJt	021	285		A81)		0290015	61	
12136	AFPB	93614	A9D	1439006777586BE	EA	01	2R	w	F	Н	9028	AJ1	027	206		A8D		0290014	63	
					_															
IDS/MA	FCOP	Y 2									DIT REI VALID									30 JAN 8 DAR
'IDS/MA									RT I	I - IN	VALID		JC	й		SUP		DOC	REC	DAR
	TEC 8	Y 2 MFGR	ORG 27	NSNPN 30	UI 45	QTY 47		PA	RT I	I · IN M C	VALID	DATA		SER		SUP ORG 75	AWAY 78	DOC NUMBER	REC	DAR
/UC	TEC	MFGR			45	47	49	PA P 51	C 52	M C 53	VALID SUP DAT 54	ORG	DAY 64	SER 67	SUF 10	ORG				DAR
/UC 1 4321	TEC 8 AFPB	MFGR 12	27 A9D	30	45 EA	01	49 2R	PA P 51 W	C 52 A	M C 53	SUP DAT 54 9028	ORG	DAY 64 019	SER 67 408	SUF 10	ORG 75		NUMBER	TYP	DAR
/UC 1 4321 6413	TEC 8 AFPB AFPB	MFGR 12 97961	27 A9D A9D	30 6120006625171BE	45 EA	01	49 2R	PA P 51 W	C 52 A	M C 53	SUP DAT 54 9028	ORG 61	DAY 64 019	SER 67 408	SUF 10	ORG 75 ABD		NUMBER 0290011	TYP	DAR C C

DAILY AUDIT REPORT

Figure 5-13.-VIDS/MAF Copy 1 Daily Audit Report.

DR-2									MON	THI	LY PROD	UCT	ON REP	ORT						JA	N 89
RG:	AC3																				
	Action Organization	Work Center	Type Equipment Code	Work Unit Code	Position	Action Taken	Malfunction	Fault Isolation Detection	When Discovered	Items Processed	Man-hours	Elapsed Maintenance Time	Bureau/Serial Number	Type Maintenance	Job Control Number	Date	Part Number/ Technical Directive Compliance	Action Taken Failed Parts	Malfunction Failed Parts	Quantity	Transaction Code
	ORG	wc	TEC	WUC	POS	ΤA	MAL	FID	WD	IΡ	MHRS	EMT	BUNO	TM	JCN	DATE	PART/TDC	ΑT	MALF	QTY	TF
(1) (2) (3)	AC3 AC3 SUBS	X20	AAEA AAEA M TOT	010						1 1 2	4.0 2.5 6.5		151687 151688	Å		900B 9009					01 01
(4) (5) (6) (7)	AC3 AC3 SUBS	X20	AAEA AAEA M TOT	045					••	1 1 2 4	6.0 3.5 9.5 16.0		151688 151689	A		9018 9028					01
(8) (9)	AC3	X20	AAEA	42211		С	105		J	1	1.5	1.5	151687	D	AC3022699	9022	MS9046A	R	020	2	1
(10) (11) (12) (13)	AC3 AC3 AC3 SUB		AAEA	42211 42211 42211 AL		R T S	255 814 800		Н О О	1 1 1 4	3.0 1.0 1.0 6.5	1.5 1.0 1.0	151687 151683 151683		AC3022235 AC3022083 AC3022085	9022 9022 9024					2; 18
(14) (15) (16)			AAEA M TOT.	. 46132 AL		С				1 1 5	8.5 8.5 15.0	4.0	151683		AC3022423	9023	1740096	00			4
(17)	TEC	TOTA	L.							9	31.0										
(18)	wc	IATO								9	61.0										
(19) (20)	wo ?	LATOT	. а В	CDE	F G	H J		L M	N O	P	QRS	ΤU	v w x	Υ							
(21)									•••	87	981.7										
(22) (23)	ORG	SUPP	ORT A	CTION TO	TAL TE	EC AEA		01 6.5	02	C	3 04 9.5	05	06	07	08 09						

Figure 5-14.-Monthly Production Report (MDR-2).

MD	R-3					10	вс	ON	TROL	NUN	(BER	CONSO	LIDAT	TION REI	PORT							JA	N 89
ICN	ORG: AC	3																					
	Job Control Number	Type Maintenance	Type Equipment Code	Bureau Number	Work Unit Code	Position	Action Taken	When Discovered	Malfunction Code	Fault Isolation Detection	Quantity/Items Processed	Man-hours	Elapsed Maintenance Time	Manufacturer's Code	Part Number/Serial Number/Technical Directives Compliance Identification	Action Organization	Work Center	Date	Processing	Scheduling	Repair	Total Turn Around Time	Transaction Code
	JCN	T M	TEC	BUNO	wuc	POS	A T		MAL	FID	QTY/ IP	MHRS	EMT	MFGR	PART/SER/TDC	ORG	wc	DATE	P	s	R.	А Т	TR
(1)	AC3008015	s	AAEA	151633	030		0	0	000		1	.0	.0			AC3	X20	8008					11
(2)	AC3010235	В	AAEA	151686	29313		С	α	020		1	2.5	2.5			AC3	X10	9010					12
(3)							R		020		1			26512	12468H								
(4)	AC3010309	В	AAEA	151689	73632		R	D	290		1	6.0	3.0			AC3	X60	9010					23
(5)	AC3010309	В	AAEA	151689	73632		С	D	290		ı	8.0	4.0			A90	X50	9012					32
(6)							R		450		1			06481	5A3								
(7)															A A M 025				0	0	2	1 2	
(8)										•	4	16.5	9.5										
(9)										••	4	16.5	9.5										

Figure 5-15.-Job Control Number Consolidation Report (MDR-3).

It is designed so the maintenance officer will have a record of maintenance performed on the equipment for which the maintenance officer is responsible.

TECHNICAL DIRECTIVE COMPLIANCE REPORT (MDR 4-1)

This report gives a detailed list, by organization, of technical directive compliance during the reporting period. It is designed for the maintenance control officer as an aid in scheduling and maintaining positive control of technical directive compliance actions (fig. 5-16).

MAINTENANCE ACTION BY BUREAU/SERIAL NUMBER REPORT (MDR-5)

This report consolidates all maintenance actions in bureau/serial sequence including

support equipment, technical directive compliance, and component repair at the IMA. This report is designed to provide a history of maintenance actions by bureau/serial number and is intended for organizational and intermediate level managers, analysts and maintenance officers (fig. 5-17).

MAINTENANCE ACTION BY SYSTEM AND COMPONENT REPORT (MDR-6)

This report consolidates all maintenance actions by component, including technical directive compliance. It can be used to identify troublesome systems or components within systems which are indicated by a large number of maintenance actions or excessive man-hours expended for that system or component. The report is prepared and provided to the maintenance officer (fig. 5-18).

MDR-	4-1								TECHN	ICAL	DIRE	CTIVE CO	MPL	IANCE RE	PORT							J	AN 89
JCNO	RG: A	СЗ																					
	Bureau Serial Number	Type Equipment Code E	Orrective Code Interim Z		Directive Number	Revision C.	Amendment	Part/Kit	Work Unit Code ♥	Status Code S	Items Processed Organizational P	Man-hours Organizational HRS	Items Processed Intermediate	Man-hours Intermediate SI MHRSI	Elapsed Maintenance Time M	Maintenance Level M	Action Date A	Action Organization G	Work Center S		Job Control Number CN		Transaction Code R
(1)	151688	AAEA	5	0	0047			01	13300	С	1	6.0			3.0	1	9015	AC3	120	AC3	015	061	47
(2) (3)	151688				0047			01	13162	A •	1	2.0 8.0			2.0 5.0		9015	AC3		AC3	015	061	47
(4) (5)	151688	AAEA	5	4	0046	A	1	00	64485	c •	1 1	13.0 13.0			6.0 6.0	1	9015	AC3	220	AC3	014	112	41
(6) (7) (8)	151688	AAEA	5	4	0046	A	2	01	64485	D •	1 1 3	.5 .5 21.5			.5 .5 11.5	1	9015	AC3	220	AC3	014	113	41
(9)	151689	AAEA	5	0	0047			01	13000	С	1	8.0			4.0	1	9025	AC3	120	AC3	015	060	47
(10) (11)	151689	AAEA	5	0	0047			01	13162	A •	1	3.0 11.0			3.0 7.0	1	9025	AC3	210	AC3	015	060	47
(12) (13)	151689	AAEA	5	4	0046	A	1	00	64485	D •	1 1	.5 .5			.5 .5	1	9025	AC3	220	AC3	014	111	41
(14) (15) (16)	151689	AAEA	5	4	0046	A	2	01	64485	c •	1 1 3	5.0 5.0 16.5			5.0 5.0 12.5	1	9025	AC3	220	AC3	014	110	41
(17) (18) (19) (20)	151690	AAEA	6	6	0135			01	96A10	C	6	38.0	1 1 1	2.5 2.5 2.5 2.5	2.5 2.5 2.5 26.5	2	9025	A98	820	AC3	016	006	47

Figure 5-16.-Technical Directive Compliance Report (MDR 4-1).

MDF	₹-5						MAII	YTE	NANC	ACT	10N B	Y BU	REA	U/SERIA	LNUM	BER	REPORT				J#	N 89
JCN	ORG:	AT1																				
	Type Equipment Code	BureauSerial Number	Type Maintenance	Work Unit Code	Manufacturers Code	Position	When Discovered	Action Taken	Malfunction	Fault Isolation Detection	Organization	Work Center	Items Processed Organizational	Man-hours Organizational	Elapsed Maintenance Time Organizational	Items Processed Intermediate	Man-hours Intermediate	Elapsed Maintenance Time Intermediate	Job Control Number	Date	Part Number/Technical Directive Compliance Code	Transaction Code
	TEC	BUNO	TM	WUC	MFGR	POS	WD	ΑT	MAL	FID	ORG	wc	IPO	MHRSO	EMTO	IPI	MHRSI	EMTI	JCN	DATE	PART/TDC	TR
(2) (3)	APBD APBD	161011 161011 161011 STEM 1	B	4214100 4214120 4214120 L			D A A	A C R	799 127 615			X20 X20 X20		3.5 7.4 10.9	3.5 3.7 7.2	1	4.0 4.0	2.0 2.0	AT1008127 AT1009131 AT1009131	9010	MS34721-14 MS34721-14	11 31 23
(6)	APBD	161011 161011 STEM T	В	42153 42153 L			D D	A C	799 615		ATI ATI	X20 X20		5.2 2.5 7.7	2.6 2.5 5.1				AT1023110 AT1027142			11
(9) (10)	APBD APBD	161011 161011 161011 STEM 1	B B	42172 4217K 42172	47315 47315		Á D A	C C R	615 127 615		ATI	X20 X10 X20	1	1.0 3.0 4.0	1.0 1.5 2.5	1	12.2	5.0	AT1015123 AT1016124 AT1015123	9016	223176 223176	31 11 23
	TM TO												6	22,6	14.8	2	16.2	7.0				
		TOTAL											6	22.6	14.8	2	16.2	7.0				
	WD TO		A 2	в с	D E	F	G	н	J 1	(L	м	N	0	P Q	R S	т	υV		х у г			
161	TEC TO	OTAL											6	22.6	14.8	2	16.2	7.0				
17:	ORG T	OTAL											6	22.6	14.8	2	16.2	7.0				
101	NO DE	FECTS	ፐር ፕ	4 1	ORGT	1 A T O		2	OR	PER	CENT		33.3	D	ATOT T	ıt	0	INT	ERCENT	.0		

Figure 5-17.-Maintenance Action By Bureau/Serial Number Report (MDR-5)

MDR-6						1	MAIN	NTEN	AN	CE A	ACTI(Вис	Y SY	ST	EM AN	D C	OMP	ONENT REPO	RT			J	AN 89
ORG:	Work Unit Code	Position	Type Equipment Code		Bureau/Serial Number		Action Taken	Malfunction		Fault Isolation Detection	When Discovered	Type Maintenance		Itams Processed	Man-hours		Elapsed Maintanance Time	Job Control Number	Completion Date	Manufacturer's Code	Part Number/Technical Directive Compliance Code	Work Center	Transaction Code
	wuc	POS	TEC	В	סאט		ΑT	MAI	LFI	ID	WD	TM	10	P	MHRS	E	тма	JCN	DATE	MFGR	PART/TDC	wc	TR
(1) (2)	011 COMPONE	NT TO	APBE TAL	>								A	2	15 15	289.3 289.3							X10	Q 1
(3) (4) (5) (6) (7) (8)	031 032 COMPONE SUBSYSTE AT TOTAL TEC TOTA 4231100	TOT ME	ΓAL	c	E	J	K A	L 799	N	P	Q D	C D R B	2 4	20 92 12 27 T 27	142.5 118.7 261.2 550.5 Y 550.5 1.3	z	0 1.3	AT1004121	9004			X10 X10	01
(LG) (LL) (LL) (12)	4231100 4231100 COMPONE	OT TO	APBE	16	1012	- 1	Ĉ R	127 374			B	B		1 1 3	1.0 4.4 6.7		.5 2.2 4.0	AT1010276 AT1023317	9011 9024	96906	MS24213-Q42	X20 X20	23
(13) (14) (15) (16)	4231210 4231210 COMPONE SUBSYSTE						A C	127 070			J D	B D		1 1 2 5	4.8 3.6 8.4 15.1		2.4 1.2 3.6 7.6	AT1007537 AT1027426 МНЛР.3.0	9008 9027			X20 X20	11
(17) (18)	AT TOTAL	A 2	В	C 2	Ε	J	ĸ	L	N	P	Q	R 1	S	Т	Y	Z	0						
(19) (20)	42810 COMPONE	OT TH	APBE	16	31007		С	615			М	G		1	6.6 6.6		3.3 3.3	AT1018A08	9018			X20	11
(21)	SUBSYSTE	тот ма	ΓAL											1	6.6		3.3	MH/IP - 6.6					
(22) (23)	AT TOTAL	^	В	C	E	J	ĸ	L	N	P	Q	R	s	Т	Y	Z	0						
(24)	TEC TOTA	L												6	21.7		10.9						
(25) (26)	WDTOTAL		B i	С	D 3	ε	F	G	H	J 1	K	L.	M	N	0	P	Q	R S T	u v	w x	Y		

Figure 5-18.-Maintenance Action by System and Component Report (MDR-6).

COMPONENT REPAIR/BEYOND CAPABILITY OF MAINTENANCE (BCM) REPORT (MDR-7)

This report provides a spread of action taken codes for maintenance actions taken by the intermediate level and provides the maintenance officer and the maintenance/material control officer with an overview of the entire production effort of the activity by work center and work unit code within a type equipment (fig. 5-19). The report can be used to determine the percentage of components received at the intermediate maintenance activity (IMA) that do not require any repair.

FAILED PARTS/PARTS REQUIRED REPORT (MDR-8)

This report is prepared from data submitted on the VIDS/MAF with transaction code 12 or

32 and a malfunction code (not 000) entered in the (H-Z) Failed/Required Material block (fig. 5-20). This report is intended for the maintenance officer, material control officer, and work center supervisors. The report can be used to identify part numbers that have a high awaiting parts (AWP) time.

REPAIR CYCLE DATA REPORT (MDR-9)

This monthly report is a detailed list, by organization, showing the number of days of turnaround time and the elements that compose the turnaround time for each repairable component processed through the intermediate maintenance activity as documented on the VIDS/MAF, or Metrology Equipment Recall (METER) card (fig. 5-21). This report can be used to identify components that appear repeatedly in the intermediate level repair cycle.

MDR-					COMP	ONEN	r REPA	IR/BEYOND	CAPA	BII	LIT	r 01	Р М.	AIN	TEN	AN	CE F	REPO	ORT						JAN
ORG:	Action Organization	Job Control Number	Work Center	Work Unit Code	Position	Type Equipment Code	Manufacturer's Code	Part Number								Total Items Not Repaired					Total Items Repaired	Other Codes	Total Items Processed	Total Man-hours	Total EMT
		JCNORG		WUC	POS	TEC	™ MFGR		1	2	3	4 5	6	7	8 9			A E	всј	ΚZ	RPR		TOT		H EMT
1)	A9F	ATI	431	3251366				TF3400-4											t .		1		1	. 2	1
2)				WUC/TEC	JUCNU	ORG TO	IAL												1		1		1	2	1
(3)	A9F	АТ3	431	325136C				390897-2	1								1						1	4	2
4)				WUC/TEC	MCNC	RG TO	TAL		1								1						1	4	2
5)	A9F	AT5	431	3251200		APBC	54331	4418-31											1		1		1	1	1
6)	A9F	AT5	431	3251200				4418-32											3		3		3	5	4
71	A9F	AT5	431	3251200				4418-33A											1		1		1	1	1
8)				WUC/TEC	JJCN0	RG TO	ΓAL												5		5		5	7	6
9)	A9F	AT5	431	3251200		APBD	54331	4418-33A				ì			1		2	1	2		3		5	14	10
10)				WUC/TEC	JCNC	RG TO	ral					1			1		2	1	2		3		5	14	10
111						WC TO	TAI,		1			1			1		3	1	8		9		12	27	19
12)						DIVISI	ON TOT	`AL	1			1			1		3	1	8		9		12	27	19
13)						000.		ON TOTAL	1			ı			1		3	1	8		9		12		19

Figure 5-19.-Component Repair/Beyond Capability of Maintenance (BCM) Report (MDR-7).

MDR	-8								F	AILED PA	RTS/PAR	TS REQ	JIRED RE	PORT								JA	N 8
RG:	ASC	•																					
	Action Organization	Work Center	Work Unit Code	Position	Type Equipment Code	Type Maintenance	Action Taken	Malfunction	When Discovered	Bures w Serial Number	Part Number	Manufacturer's Code	Reference Symbol	Quantity	Job Control Number	Completion Date	Priority	Date Ordered	Requisition Number	Date Received	Failed Parts	Awaiting Parts Indicator	Transaction Code
																		DATI		DATE		A	
	ORC	wc	WUC	POS	TEC	TM	ΑT	MAL	wp	BUNO	PART	MFCR	REFSYM	QTY	JCN	DATE	PRI	ORD	REQN	RECD	P	W	TI
1)	A9D	650	7363100		AAEA	В	R	649	D	141687	3537A-0	82227	527	1	AC3007626	9008	03	9007	G973	9007	1		32
2)	A9D	650	7363100		AAEC	В	R	561	н	151776	3537A-0	82227	527	1	AB3020622	9029	03	9021	G735	9029	1	1	32
1)											P	ART TO	TAL	2									
()	A9D	650	7363200		AAEA	В	R	450	D	151687	866542	49671	523	1	AC3004763	9008	03	9005	G974	9007	1	ı	32
5)	A9D	650	7363200		AAEA	G	R	450	M	151689	866542	49671	523	1	AC3010A17	9029	03	9010	G988	9028	1	1	32
5)	A9D	650	7363200		AAEC	В	4	602	E	151778	866542	49671		1	AC3023844	9030	03	9029	G910	9029	1	ì	32
7) -											P	ARTTO	TAL	3									
8)	QEA	650	73 X 2 P 0 0	,	AAEA	В	R	958	D	151776	866554	29146	381	1	AC3006612	9029	03	9006	G975	9028	1	1	32
9)	A9D	650	73X2P00	,	AAEA	В	R	064	Н	151778	86G554	29146	381	1	AC3010819	9018	03	9011	G990	9011	1		32
10)	A9D	650	73X2P00)	AAEC	В	R	450	D	151834	866554	29146	381	1	AC3019436	9028	03	9019	G907	9027	1	1	3:
11)	A9D	650	73X2P00)	AAEC		R	602	N	151879	866554	29146	381	ı	AB3022B20	9027	03	9022	G744	9026	1	L	32
12)											P	ARTTO	TAL	4									
131	A9D	650	73X4C10)	AAEA	В	R	450	D	151776	869993	72726	734	1	AC3019437	9028	03	9019	G908	9027	1	1	31
14)	A9D	650	73X4C10)	AAEC	В	R	561	D	151778	869993	72726	734	ı	AB3022921	9027	03	9022	G745	9026	1	1	32
151											P	ART TO	TAL	2									

Figure 5-20.-Failed Parts/Parts Required Report (MDR-8).

MDR-9							RE	PAIRC	YCL	E DAT	A RE	PORT								•	AN 89
ORG:	D Action Organization	Work Center	Part Number	Type Equipment Code	Component Seriel Number	Job Control Number	Work Unit Code	Malfunction Code	Items Processed	Action Taken	Transaction Code	Elapsed Maintenance Tinte	Man-hours	Processing	Scheduling	Repair	Awaiting Parts	In Work	TAT AMI	Total Turneround Time	Completion Date
	ORG	wc	PART	TEC	SER	JCN	wuc	MAL	. IP	ΑT	TR	EMT	MHRS	PRO	SCH	REP	AWP	WORK	IMA	тот	DATE
	A9D	610	1267 1267 1267	AAEA AAEA	2276A	AC3003022 AC3003214 AC3004110	7236400 7236400 7236400	127 255 962	1 1	C C	31 32 32	8.4 4.4 1.8	16.8 13.2 5.4	3 1	1	1 1 1	1	1 2 1	1 2 2	4 3 2	900i 900i 900i
	TEC?								3			14.6	35.4	4 1.3	1 .3	3 1.0	.3	4 1.3	5 1.7	9 3.0	
				AAEC AAEC		AC3003021 AC3004421	7236400 7236400	806 127	1	A C	31 32	1.1 1.7	2.2 5.1			1		1	í 1	1	900
	TEC								2			2.8	7.3	.0	.0	2 1.0	.0	2 1.0	2 1.0	1.0	
			MBER 7	TOTAL AVERAC	DE .				5			17.4	42.7	4 .8	.2	5 1.0	1 .2	6 1.2	7 1.4	1 2.2	
			NTER'	TOTAL AVERA	GE				5			17.4	42.7	.8	1 .2	5 1.0	1 .2	6 1.2	7 1.4	11 2.2	
	ORG ORG		AL RAGE					3	064			734.5	11466.4	3370 1.1	2451 .8	4289 1.4	7660 2.5	119491 3.9	4400 1 4.7	7770 5.8	
	TOTA	L TI	ME IN	DAYS	0-3 RFI B0 1265 - 6		11-2 RFI B 230		21. RFI 61	30 BCM 51		-60 BCM 58	61-90 RFI BCM 48 2:	(R	91-120 FI BC!	A RI	121-150 FI BCM	r RF	ER 150 IBCM 9		

Figure 5-21.-Repair Cycle Data Report (MDR-9).

FOREIGN OBJECT DAMAGE (FOD) REPORT (MDR-10)

This report is used to measure the maintenance effort attributable to FOD. Components replaced, repaired, condemned, etc., can be identified by the data in the MDR file. Indirectly, the report reflects housekeeping conditions (cleanliness of ramps, runways, hangar area, etc.) or the maintenance methods of personnel (adherence to proper maintenance practices (fig 5-22). The source of data for this report is the VIDS/MAF (excluding transaction code 72), which contains malfunction code 301.

CORROSION CONTROL/TREATMENT REPORT (MDR-11)

This report is designed for monitoring the Corrosion Control Program or for investigating the amount of corrective corrosion treatment necessary (fig. 5-23). Support action code 04 and malfunction code 170 are the two sources of

information that are used to identify these areas. It is a simple matter to determine whether any specific portion of the aircraft, by work unit code, needs a better corrosion control program. This report is subject to change due to the deletion of the Support Action Form (SAF).

NO DEFECT REPORT (MDR-12)

This report shows the amount of time and effort expended on maintenance for which there is no malfunction (fig. 5-24). This report can be used to determine man-hours expended in removing or installing items with no known malfunction, solely to facilitate other maintenance.

WHEN MALFUNCTION WAS DISCOVERED REPORT (MDR-13)

This report shows the action taken by category of each when discovered code

MDR.	10							FOF	REIGN	OB	IECT DA	MAGE R	EPORT					JA	N 8
ORG:	AC3																		
	Work Unit Code	Position	Type Equipment Code	BureawSerial Number	When Discovered	Type Maintenance	Action Taken	Malfunction	Fault Isolation Detection	Items Processed	Man-hours	Manufacturers Code	Part Number	Reference Symbol	Job Control Number	Action Organization	Work Center	Completion Date	Transaction Code
	WUC	POS	TEC	BUNO	WD	тм	ΑT	MAL	FID	IP	MHRS	MFGR	PART NUMBER	REFSYM	JCN	ORG	wc	DATE	
(1)	11421		AAEA	151687	E	В	R	301		1	4.5	26512	128H100555		AC3022622	AC3	120	9022	23
(2)	11421		AAEA	151687	E	В	С	301		1	12.0	26512	128H100555		AC3022622	A9D	540	9023	32
(3)							R	301				26512	128H41	215					
(4)	14814		AAEA	151688	E	В	c	301		i	2.5				AC3022629	AC3	120	9022	11
(5)	23500		AAEA	151689	J	В	С	301		1	5.0				AC3024024	AC3	110	9024	12
(6)							0	000				JHHAI	673498 E1425						
(7)	23500		AAEA	151689	С	В	R	301		1	16.0	JHHAI			AC3025123	AC3	110	9026	23
(8)	23500		AAEA	151689	C	В	C	301		1	122.0	JHHA1			AC3025123	A9D	410	9026	32
(9)							R	301				73481	135HA10						
(10)	2358100		AAEA	151690	J	В	R	301		1	2.0	77224	184A150		AC3025127	AC3	110	9026	25
(11)								000				JHHAI	673473 E0258						
(12)	2358100		AAEA	151690	j	В	C	301		1	10.0	77224	184A150		AC3025127	A9D	410	9026	32
(13)							R	301				77224	184A150-1						
(14)									•		174.0								
(15)									**	8	174.0								

Figure 5-22.-Foreign Object Damage Report (MDR-10).

DR-11 RG: AC3							COR	ROSIC	N CO	NTR	OLTREA	TME	NT F	EPORT	•				M	AY 89
NO. AGE	Work Unit Code OC	Position POS	Type Equipment Code E	BureawSerial Number 20	When Discovered	Type Maintenance A	Action Taken A	Malfunction MA	Fault Isolation Detection	Items Processed -	Man-hours MHRS	Elapsed Maintenance Time M	Maintenance Level M	Completion Date TE	Manufacturers Code GR M	Part Number Part number	Action Organization & O	Work Center S	Job Control Number S	Transaction Code T
411	040			151692		٨				23	61.5		1				ACS	X10		01
(1)	040			151692		Â				21	15.0		1				AC3	X2A		01
(2)	041			151692		Ä				6	5.0		1				AC3	X60		01
(3) (4)	048			151692		Ä				8	10.0		1				AC3	X3A		01
(5)	049			151692		Ä				2	6.0		1				AC3	X10		0
(6)	049		AABA	131031					٠	60	97.5									
(7)	1111C		AAEA	151692	F	В	Z	170		2	4.0		1						AC3122636	11
(8)	1111C		AAEA	151692	J	D	2	170		1		1.0	1	9122			AC3		AC3122011	1
(9)	1111C		AAEA	151692	M	G	Z	170		1		1.0	1	9122			AC3	X2C	AC3122A30	1
(10)									•	4	6.0	6.0								
(11)	11930		AAEA	151692	J	D	Z	170		1		3.5	1	9122			AC3	X20	AC3122012	ì
. (12)									•	1	3.5	3.5								
(13)	11221		AAEA	151692	F	В	z	170		1	2.0	2.0	1	9122					AC3122637	1
(14)	11221			151692	Ř	В		170		1	1.5	.9	1	9122			AC3	X10	AC3122009	1
(15)					•	_			٠	2	3.5	2.9								
(16)	2951C		AAEA	151692	J	D	z	170		1		1.5	1	9122					AC3122265	1
(17)	2951C			151692	J	D	Z	170		1	3.0	3.0	1	9122			AC3	X10	AC3122061	1
(18)									٠	2	6.0	4.5								
(19)									••	69	116.5	16.9								
(20)									•••	69	116.5									

Figure 5-23.-Corrosion Control/Treatment Report (MDR-11).

MDR-12										NO	DEFECT	REP	ORT						JA	N 89
DRG:	AC3																			
	Work Unit Code	Position	Type Equipment Code	Bureau/Serial Number	When Discovered	Type Maintenance	Action Taken	Malfunction	Fault Isolation Detection	Items Processed	Man-hours	Elapsed Maintenance Time	Maintenance Level	Completion Date	Manufacturer's Code	Part Number	Serial Number	Work Center	Job Control Number	Transaction Code
	WUC	POS	TEC	BUNO	WD	MT	ΑT	MAL	FID	IP	MHRS	EMT	ML	DATE	MFGR	PART NUMBER	SERIAL	wc	JCN	TR
(1)	11910		AAEA	151687	E	В	A	799		1	1.5	1.5	1	9022				X20	AC3022431	11
(2)	11A10			151687	E	В	A	799		1	.5	.5	1	9022					AC3022435	11
(3)	11A21			151685	J	D	A	799		1	1.0	1.0	1	9022				X 20	AC3022102	11
(4)									•	3	3.0	3.0								
(5)	29310		AAFA	151689	J	D	A	799		1	1.0	1.0	1	9022				X10	AC3022112	11
(6)	29620			151687	В	В	Α.	799		1		.5	1	9022				X10	AC3022361	11
(7)	23020		AALA	10100	_		••		•	2		1.5								
(8)									••	5	4.5	4.5								
(9)	1122110		4 4 F 4	151686	0	В	s	800		1	3.0	1.5	1	9022				X30	AC3022023	11
(10)	1122110	'	VUEV	151000	•		Ü	000		1		1.5	-	• • • • •						
(11)									••	1		1.5								
(11)																				
(12)	12110		AAEA	151698	0	В	S	804		1		1.5	1	9022				X30	AC3022315	11
(13)									•	1		1.5								
(14)									••	1		1.5			04055	.0166	193742	X20	AC3022019	11
(15)	51114			151686	0	В	T	814		1		1.0	1	9022 9022		A2165 18744			AC3022020	16
(16)	51114		AAEA	151686	0	В	т	814		l		1.0 2.0	1	9022	82430	10144	מבבוווטמ	A 20	1100041010	• • • • • • • • • • • • • • • • • • • •
(17)										2		2.0								
(18)									•••	2	2.0	2.0								
(19)									•••	9	13.0	9.5								

Figure 5-24.-No Defect Report (MDR-12).

(fig. 5-25). This report is prepared from data submitted on the METER card and the VIDS/MAF, excluding transaction codes 00, 02, 03 and 72. This report is intended for use by the maintenance officer. The report can be used to determine how many abort malfunctions were caused by mechanical failures, what caused them, whether these malfunctions were discovered before flight or while in flight, and whether they could have been eliminated by better inspections of the aircraft.

MONTHLY EQUIPMENT DISCREPANCY AND UTILIZATION REPORT (SCIR-3)

This report is designed to show, by bureau/ serial number, the total number of discrepancy hours that limited the equipment from performing its assigned mission or function during the reporting period (fig. 5-26). The report is designed for the maintenance officer and may be used to determine the impact of maintenance/supply on the mission capability of the equipment. Equipment in/out of service hours, flight hours, and number of flights are also shown.

MONTHLY EQUIPMENT CAPABILITY REPORT (SCIR-4)

This report is designed to reflect equipment capability to perform its assigned mission/function during a reporting period (fig. 5-27). This report is prepared from VIDS/MAF documents that have a valid equipment operational capability (EOC) code documented in the Repair Cycle or Maintenance/Supply Record. This report reflects percent of mission capability of equipment by bureau/serial number and overall totals for that type of equipment.

MONTHLY EQUIPMENT MISSION CAPABILITY SUMMARY REPORT (SCIR-5-1)

This report is designed to display SCIR hours by mission category and awaiting maintenance

MDR-13					W	IEN MAI	LFUNCT	ON WAS DI	SCOVERED REPORT				JAN 8
RG: A	AC3												
	Type Equipment Code	When Discovered	Work Unit Code	Position	Action Taken	Malfunction Description	Fault Isolation Detection	Job Control Number Organization	Action Organization		Items Processed	Man-hours	Elapsed Maintenance Time
	TEC	WD	WUC	POS	AT	MAL	FID	JCNORG	ACTORG		IP	MHRS	EMT
(1) (2) (3)	AAEA AAEA	B B	76931 76931		R C	561 127		AC3 AC3	AC3 AC3	••	2 5 7	1.0 5.0 6.0	1.0 5.0 6.0
(4) (5)	A B	C J 5	K L	N P	QR 2	ѕ т	Y Z	0		***	7	6.0	6.0
(6) (7) (8)	AAEA AAEA	a a	29313 29313		C R	167 020		AC3 AC3	AC3 AC3	••	1 1 2	4.0 6.0 10.0	2.0 3.0 5.0
(9) (10)	AAEA	D	41171		R	167		AC3	AC3	••	1	6.0 6.0	3.0 3.0
(11)	AAEA AAEA	D D	46634 46634		B C	105 070		AC3 AC3	AC3 AC3		3 1	2.5 .5	2.5 .5
(13) (14)	AAEA	D	72361		R	383		AC3	AC3	••	4 2 2	3.0 1.5	3.0 1.5
(15) (16)	AAEA	D	73364		R	383		AC3	AC3	••	2	1.5 1.5	1.5 1.5
(17) (18) (19)	A B 3	C J	K L	N P	Q R	S T	y z	0		•••	2	1.5 22.0	1.5
(20)	AAEA AAEA	E E	11921 11921		B C	381 381		AC3 AC3	AC3 AC3		3 2	12.0 10.0	5.0 10.0
(22)	AAEA	E	11921	N P	R	381	v e	AC3	AC3	**	1 6	6.0 28.0	3.0 18.0
(24) (25) (26)	A B	C J 2	K L	N P	Q R	S T	Y Z	0		***	6 24	28.0 56.0	18.0 38.0

Figure 5-25.-When Malfunction Was Discovered Report (MDR-13).

SCIE	₹-3				N	ІНТИОІ	Y EQU	IPMEN:	DISCF	REPANC	YAND	UTILIZ.	ATION	REPORT					MAY 8
iCN	ORG - AF	, P	UC - 00	10029											то	TAL	\$H	POP	TOTAL
	BUNÔ	Type Equipment Code	Not Mission Capable/Scheduled	Not Mission Capable/Unscheduled	Not Mission Capable Supply	Partial Mission Capable Maintenance	Partial Mission Capable Supply Partial Mission Capable	Full Mission Capable Maintenance	Pull Mission Capable Supply	Equipment IN Service Hours	Equipment OUT Service Hours	Inventory Indication	Meter or Utilization Base	Equipment Utilization	Total Flight Hours	Total Number Flights	Ship Operation Flight Hours	Ship Operation Number Flights	Total SCIR Hours
	BUNO	TEC	SCH	NMC. UNS	SUP	PI MNT	AC SUP	FN MNT	IC SUP	EIS	EOS	INV IND	MTR /UB	EQUIP UTL	flt HRS	NR FLTS	FLT HRS	NR FLTS	SCIR HRS
(1)	157453	AAFF	117	174		9	18			744		A			6	4			1407
(2)	157587	AAFF	37	93	33	81	18			744		A			35	15	22	9	682
(3)	157593	AAFF		168	397	27	148			744		A			12	5	5	2	2877
(4)	158004	AAFF	2	632	10					744		A			8	4			1747
(5)	159657	AAFF	26	45	5	144	294			744		Α			63	21	39	14	805
(6)	159969	AAFF	2	142	2	21				744		A			29	11	10	4	245
(7)	159978	AAFF	28	92		209	41	295		744		A							1055
		•	212	1346	447	491	519	295		5208					153	60	76	29	8818
(8)		••	212	1346	447	491	519	295		5208					153	60	76	29	8818

Figure 5-26.-Monthly Equipment Discrepancy and Utilization Report (SCIR-3).

SCIR-4 ORG: /		AAFF				М	ONTHL	Y EQU	IPMENT	CAPA	BILITYI	REPORT	•						MAY 89
	Burea w Serial Number	E OH MUSSION CENTER	S. I Visit Conth						Partial Mission Capable					Not Mission Capable			Equipment IN Service Hours	Equipment OUT Service Hours	Equipment Available Hours
		FM				PEF			SION CA										
	BU/SER	Α	В	С	D	E	F	G	Н	J	ĸ	L	w	N м (Y	Z	EIS	EOS	EAH
(1)	157453	57.3			3.6											39.1	744		744
(2)	157587	64.7									10.3	3.0				22.1	744		744
(3)	157593	.4			1.7						1.9	19.9				76.0	744		744
(4)	158004	13.3														86.7	744		744
(5)	157657	30.8				41.9					14.8	2.4				10.1	744		744
(6)	159969	77.6				.4					2.4					19.6	744		744
(7)	159978	10.3	39.7			3.2					29.4	1,1				16.2	744		744
(8)	AVG	36.3	5.7		.8	6.5					8.4	3.8				38.5			
(9)	FMC: HRS	- 2193 9	6 - 42.0		P	MC: HRS	S - 1010	% - 19.	5		NMC:	HRS - 20	05 %-3	8.6		тот	5208		5208

Figure 5-27.-Monthly Equipment Capability Report (SCIR-4).

(AWM) hours by reason codes, summarized for a given EOC code and associated work unit code during a reporting period (fig. 5-28). This report is prepared from VIDS/MAF documents that have a valid EOC code documented in the Repair Cycle or Maintenance/Supply Record.

MONTHLY EQUIPMENT MISSION CAPABILITY BUREAU/SERIAL SUMMARY REPORT (SCIR-5-2)

This report shows SCIR hours by mission category and awaiting maintenance (AWM) hours by reason codes, summarized by a given EOC code and associated work unit code by bureau/ serial number (fig. 5-29). This report is prepared from VIDS/MAF documents that have a valid EOC code documented in the Repair Cycle/ or Maintenance/Supply Record.

MONTHLY MISSION AND MAINTENANCE DATA DETAIL BY BUREAU/SERIAL REPORT (SCIR-5-3)

This report is designed to show mission capability and maintenance data for each

VIDS/MAF submitted for a given EOC code and associated work unit code by bureau/serial number within type equipment code and job control number organization (fig. 5-30).

MONTHLY MAINTENANCE SUMMARY

After the analyst masters and develops his or her own analysis techniques and becomes familiar with all of the Maintenance Data System (MDS) reports and their individual uses, then it is time to arrange the data in a format so that all maintenance personnel can easily understand the data presented.

To be of practical use to management, summarized reports must be compiled, studied, and analyzed by all supervisory personnel in the maintenance activity. The most common format for presenting equipment maintenance and utilization data on a monthly basis is the monthly maintenance summary. The monthly maintenance summary provides a coordinated combination of

SCIR-5	- 1				MON	THLYE	QUIPM	ENT MI	SSION	CAPA	BILITY	SUMMAR	RYREF	ORT		-			MAY 89
	AAFF	assumei)		70												DA PA	TE: 05/3 GE: 01	31/89
Equipment Operational Code	Work Unit Code	Total SCIR Hours	Full Mission Capable Hours Maintenance	Full Mission Capable Hours Supply	Partial Mission Capable Hours Maintenance	Partial Mission Capable Hours Supply	Not Mission Capable Hours Scheduled	Not Mission Capable Hours Unscheduled	Not Mission Capable Hours Supply					AWM Hours by Reason Code					Total AWM Hours
EO	c wuc	TOTAL SCIR HOURS	FMC MNT	HRS SUP	PMC MNT	HRS SUP	SCH NI	MC HRS	SUP	t	AWAI	TING MA	INTER	NANCE	BY REAS	SON CO	DES 8	0	TOTAL
(1) B5 (2) B5 (3) B7 (4) • T (5) PE	7 573M3	5 001371 43 1419 100.0	5 10 25 40 2.8	1361 18 1379 97.2	.0	.0	.G	.0	.0	.0	.0	4 4 100.0	.0	.0	.0	.0	.0	.0	4 4 100.0
		1575 508 2083 100.0	.0	.0	154 10 164 7.9	1421 498 1919 92.1	.0	.0	.0	.0	83 83 98.8	.0	.0	.0	.0	.0	.0	1 1 1.2	84 84 100.0
(10) Z2: (11) Z4: (12) Z4: (13) Z4: (14) Z5: (15) Z5: (16) * T: (17) PE	2 42A6B0 2 42A650 5 45211 1 51143 1 51430		.0	.0	.0	.0	0	322 8 20 40 320 40 750 70.4	315 315 29.6	72 3 75 12.6	150 150 25.2	20 20 40 6.7	.0	90 90 15.1	240 240 40.4	.0	.0	.0	312 3 20 240 20 595 100.0
18) *** 19) PE	TOTAL RCENT	4567 100.0	40 .9	1379 30.2	164 3.6	1919 42 .0	.0	750 16.4	315 6.9	75 11.0	233 34.1	44 6.4	.0	90 13.2	240 35.1	.0	.0	.2	683 100.0
		4567	40	1379	164	1919		750	315	75	233	44		90	240			1	683

Figure 5-28.-Monthly Equipment Mission Capability Summary Report (SCIR-5-1).

SCIR-	5.2				MONTH	LY EQU	JIPMEN	IT MISS	ION CA	PABILI	TY BU	REAU	SERIALS	UMMA	RYRE	PORT				MAY 89
ORG: TEC:	A F	r4 App		Full		Partial	70	z	Not				U/SERIA DECIMAI			57453			FE: 05/31 JE: 01	1/89
Equipment Operational Code		Work Unit Code	Total SCIR Hours	Full Mission Capable Hours Maintenance	Full Mission Capable Hours Supply	Partial Mission Capable Hours Maintenance	Partial Mission Capable Hours Supply	Not Mission Capable Hours Scheduled	Not Mission Capable Hours Unscheduled	Not Mission Capable Hours Supply					AWM Hours by Reason Code					Total AWM Hours
	EOC		TOTAL SCIR HOURS	FMC MNT	HRS SUP	PMC MNT		sch N	MC HRS UNS	SUP	1	AWAI	TING MA	INTEN 4	ANCE I	BY REAS	SON CO	DES 8	0	TOTAL
2) 1 3) 1 4) 1	851 857 872 TOT PERC	51141 573M300 72382 FAL CENT	1371 43 1419 100.0	5 10 25 40 2.8	1361 18 1379 97.2	.0	.0	.0	.0	.0	.0	.0	4 4 100.0	.0	.0	.0	.0	.0	.0	4 4 100.0
7) 1	144 L73 • TO	44112 73662 FAL CENT	1575 508 2083 100.0	۵.	.0	154 10 164 7.9	1421 498 1919 92.1	.0	.0	.0	.0	83 83 98.8	.0	.0	.0	.0	.0	.0	1 1 1.2	84 100.0
10) 11) 12)	Z23 Z42 Z42	23500 42A6B00 42A6500	637 8 20						322 8 20 40	315	72 3		20			240				312 3 20
	251 251 • TO	45211 51143 51430 TAL CENT	40 320 40 1065 100.0	.0	.0	.0	.0	.0	320 40 750 70.4	315 29.6	75 12.6	150 150 25.2	20 40 6.7	.0	90 90 15.1	240 40.4	.0	.0	.0	240 20 595 100.0
		OTAL CENT	4567 100.0	40 .9	1379 30.2	164 3.6	1919 42.0	.0	750 16.4	315 6.9	75 11.0	233 34.1	44 6.4	.0	90 13.2	240 35.1	.0	.0	.2	683 100.0
		OTAL CENT	4567 100.0	40 .9	1379 30.2	164 3.6	1919 42.0	.0	750 16.4	315 6.9	75 11.0	233 34.1	44 6.4	.0	90 13.2	240 35.1	.0	٥.	.2	683 100.0
		TOTAL CENT	4567 100.0	40 .9	1379 30.2	164 3.6	1919 42.0	.0	750 16.4	315 6.9	75 11.0	233 34.1	44 6.4	.0	90 13.2	240 35.1	.0	.0	.2	683 100.0

Figure 5-29.-Monthly Equipment Mission Capability Bureau/Serial Summary Report (SCIR-5-2).

SCIR- ORG: TEC:		BUF NOT	REAUS	ERIAL	NUMBE	R: 1574	53			ta detail by e data, mainte									E: 05/3 E: 01	MAY 89 1/89
Equipment Operational Code	Work Unit Code	Total SCIR Hours	Full Mission Capable Hours Maintenance	Full Mission Capable Hours Supply	Partial Mission Capable Hours Maintenance	Partial Mission Capable Hours Supply	Not Mission Capable Hours Scheduled	Not Mission Capable Hours Unscheduled	Not Mission Capable Hours Supply	Job Control Number	Work Center	Transaction Code	When Discovered	Type Maintenance	Action Taken	Malfunction Code	Items Processed	Man-hours	Elapsed Maintenance Time	Document Number
		TOTAL	FMC		PMC	HRS	TY DAT	MC HRS					W	Т	ANC A T	E DA1				
E		SCIR HOURS	MNT	SUP	MNT	SUP	SCH	UNS	SUP	JCN	WC	TR		M		MAL			EMT	DOCNUM
(2) E	51 51141 57 573M300 572 72382 TOTAL	5 1371 43 1419	5 10 25 40	1361 18 1379						AF4 123 869 AF4 128 196 AF4 129 243	210 220 220	11 23 23	D D	B B	C R R	127 374 374	01 01	1.0 1.5 2.1	.5 1.0 2.1	DTM0562 DTM2113 DTM0894
(5) F (6) J (7) J (8) J (9) L	PERCENT 44 44112 44 44112 44 44112 .73 73662	100.0 1318 16 241 508	2.8	97.2	.0 16 13 125 10	.0 1302 3 116 498 1919	.0	.0	.0	AF4 133 905 AF4 137 035 AF4 136 947 AF4 150 044	230 230 230 220	18 23 23 23	0 Y H J	B B B	T R R	814 169 169 374	01 01 01 01	3.2 2.6 8.2 1.2	1.6 1.3 4.1 1.0	BVV0418 DGK8584 DGK8711 BLM6842
	42 42A6B00 42 42A6500 45 45211 51 51143 51 51143	2083 100.0 637 8 20 40 30 290 40	.0	.0	7.9	92.1	.0	.0 322 8 20 40 30 290	.0 315	AF4 141 999 AF4 147 081 AF4 147 082 AF4 143 868 AF4 149 214 AF4 143 900 AF4 143 867	12B 220 110 220 110 110	11 11 11 11 12 12	0000000	B B B B	SCCBACC	800 450 127 160 799 127 334	01 01 01 01 01 01	2.0 .5 6.0 2.0 6.0 10.0 4.0	1.0 .5 2.0 1.0 3.0 5.0 2.0	BVV0405 DTM0820 DTM0821 DTM1180 DTM0881 DTM0964 DTM1181
(19) (20) F (21) (21) (23) (24) F (25) (25)	PERCENT PERCENT PERCENT PERCENT PERCENT PERCENT PERCENT	1065 100.0 4567 100.0 4567 100.0 4567 100.0	.0 40 .9 40 .9	.0 1379 30.2 1379 30.2 1379 30.2	.0 164 3.6 164 3.6 164 3.6	.0 1919 42.0 1919 42.0 1919 42.0	.0 .0 .0	750 70.4 750 16.4 750 16.4 750 16.4	315 29.6 315 6.9 315 6.9 315 6.9											

Figure 5-30.-Monthly Mission and Maintenance Data Detail by Bureau/Serial Report (SCIR-5-3).

MDS reports to highlight specific problem areas and improve overall maintenance management. Trends may be detected and corrected before they reach crisis levels through analysis over a period of time.

The monthly maintenance summary contains various displays; for example, charts, graphs, and tables that are used to present the results of analysis. Several examples of the various charts, graphs, and tables that are used in the monthly maintenance summary are contained in the latest edition of OPNAVINST 4790.2.

CHAPTER REVIEW QUESTIONS

- Q1. What are the maintenance personnel assigned to quality assurance/analysis known as?
- Q2. What does NAMDRP stand for?
- Q3. What report provides a standard system for reporting explosive incidents?
- Q4. What report provides maintenance activities with a method for reporting deficiencies in new or newly reworked material?
- Q5. What form do you use to submit a category II (CAT II) Technical Publication Deficiency Report (TPDR)?
- Q6. An Aircraft Discrepancy Report (ADR) must be submitted not later than how many days after receipt of the aircraft?
- Q7. What report should you submit if a technical publication deficiency is detected that if not corrected, could result in death or injury to personnel?
- Q8. The data analyst must be a senior petty officer and formally trained in what?

- Q9. What is the function of analysis?
- Q10. What process involves the detailed study of all of the data?
- Q11. What form is used to submit source documents to the data services facility (DSF)?
- Q12. What action does the DSF take if a document is found to be illegible?
- Q13. What method is used to correct data in the VIDS/MAF A-Z record?
- Q14. What data is contained on part I of the VIDS/MAF copy 1 Daily Audit Report (DAR)?
- Q15. What report provides the work center supervisor with statistical data pertaining to the work center?
- Q16. What report can be used to identify part numbers that have a high awaiting parts (AWP) time?
- Q17. What report indirectly reflects house-keeping conditions?
- Q18. What report shows the amount of time and effort expended on maintenance for which there is no malfunction?
- Q19. What report is designed to reflect equipment capability to perform its assigned mission/function during a reporting period?
- Q20. What is the most common format for presenting equipment maintenance and utilization data on a monthly basis?